

Additional Funding Request

MD048	CSS# 28167 WO# 13440 Asset# NA							
Description of Repairs	S&S proposes to install a new thermostat in zone 4. S&S will then complete a system check to ensure system is running as intended.							
Diagnosis: Initial Work Order	Need to have the rooftop HVAC unit for zone 4 serviced as a requirement to vacate the facility as per the lease agreement. These tenants are currently either moved out or are in the end process of moving out and access to the building will need to be scheduled with me.							
Diagnostic Fee	\$ 250 Labor \$100/hr x 2.5							
Additional Labor Cost to Perform Repairs	\$ 600 Labor \$100/hr x 6							
Additional Material Cost to Perform Repairs	\$ 34.79 <table border="1"><tr><td>Thermostat/TH2110DH1002</td><td>1</td><td>34.79</td><td>34.79</td></tr></table>				Thermostat/TH2110DH1002	1	34.79	34.79
Thermostat/TH2110DH1002	1	34.79	34.79					
Total Cost of Repair	\$ 884.79							



S&S MECHANICAL

S&S Mechanical
4831 South Crain Highway
Upper Marlboro, MD 20772

Tel. 1 - (301) 574-1555
Fax. 1 - (301) 574-1558
www.sandsmidatlantic.com

CUSTOMER QUOTATION NO. 480

Tidewater, Inc.
Tidewater, Inc
6625 Selnick Dr.
Suite A
Elkridge MD 21075

Quote Name: 13340
Quote No: 480
Site: MD048 Continental Drive
Site Contact:
Salesperson: Lindsay Ruby
Created Date: 01/14/2021
Valid For: 30 Day(s)

WO#: 13340

CSS Ticket Number: 28167

SOW: Need to have the rooftop HVAC unit for zone 4 serviced as a requirement to vacate the facility as per the lease agreement.

S&S was onsite and found operations in zone 4 checked good but need a thermostat installed in the class room.

S&S proposes to install a new thermostat in zone 4.

S&S will then complete a system check to ensure system in running as intended.

Service

Item	Quantity	Unit Price	Total
Thermostat/TH2110DH1002	1.00	\$34.79	\$34.79
Diagnosis Fee	1	\$250.00	\$250.00
HVAC Labor Rate	6	\$100.00	\$600.00
Sub-Total ex Tax			\$884.79
Tax			\$0.00
Total inc Tax			\$884.79

Labor	\$850.00
Materials	\$34.79
Sub-Total ex Tax	\$884.79
Tax	\$0.00
Total inc Tax	\$884.79

**CERTIFICATION OF WORK
SERVICE CALL**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: MO-48 Date of Visit: 1/13/2021

Contractor Personnel on Site:

- | | |
|---------------------------|----------|
| 1. <u>Brian Davis</u> | 4. _____ |
| 2. <u>Jeremy Sneathen</u> | 5. _____ |
| 3. _____ | 6. _____ |

Service Call Number

CSS# 13340 WO# 28167


Description of Repairs

Service Rooftop HVAC Unit for Zone 4

CERTIFICATION OF WORK

To be signed by the Contractor:


Print Name: Jeremy Sneathen Date: 1/13/2021

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: KEN August Date: 13 JAN 13

Signed: 

E-Mail: _____



Plumbing

Heating

HVAC

PEX

Fittings

Valves

Thermostats

Electrical

Resources

Our Team

Are you a Pro?

Join Our **TRADEMASTER** Program!

Exclusive Benefits, Absolutely FREE. Apply Now

Home > Heating Supplies > Thermostats > Honeywell Thermostats > PRO Honeywell Thermostats

PRO 2000 Horizontal Programmable Thermostat (1 Heat/1 Cool)

Honeywell

SKU
TH2110DH1002

Brand
Honeywell

Rating
★★★★★ (4)

\$28.99 each

ADD TO CART

In Stock

Get 442 Tomorrow, Jan 15

More Available [Inventory Details](#)


FastTrack Order by 6PM, receive tomorrow

Free Shipping

On orders over \$99

Easy Returns

No restocking fee for 90 days



Add to List

Product Info

Videos (4)

Reviews (4)

Q&A