

**CERTIFICATION OF WORK
SERVICE CALL**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: USARC VAUSD Date of Visit: May 6, 2021

Contractor Personnel on Site:

- | | |
|--------------------------|----------|
| 1. <u>Brandon Curtis</u> | 4. _____ |
| 2. _____ | 5. _____ |
| 3. _____ | 6. _____ |

Service Call Number

CSS# 30405 WO# 14156


Description of Repairs

Located leak on Chilled Water pipe above tee, There
was a hole on side of pipe. Installed a clamp to
patch hole. Was told there getting ready to replace
Systems as well a piping. Scott gave me the ok for Clamp.

CERTIFICATION OF WORK

To be signed by the Contractor:


Print Name: Brandon Curtis Date: May 6, 2021

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Will Sholtz Date: 5-6-21

Signed: 

E-Mail: _____



CAUTION
USE TRUCK LIFT - WORK ON ALL COPPER
NEEDS AND EXTENDED DRAIN AND VENT LINES
AND PIPING WHEN ATTACHING OR DISCONNECTING
AND PIPING. PIPING ON CAPS DO NOT EXCEED
CONNECTIONS. DO NOT EXCEED 20 FT LBS
TORQUE ON DRAIN AND VENT CONNECTIONS.
TEFLON PASTE SEALANT SHOULD NOT BE USED

43-48 OK

E3D526R

MODEL: 4172007
MAX. PRESSURE: 3.932.729
MAX. WATER PRESSURE: 3.212.424
DESIGN: 4172007
MAX. WATER PRESSURE: 3.212.424
MAX. WATER PRESSURE: 3.212.424
MAX. WATER PRESSURE: 3.212.424

THE TRANE COMPANY
LACROSSE, WISCONSIN
MANUFACTURED UNDER ONE OR MORE
OF THE FOLLOWING U.S. PATENTS:
4,172,007 3,932,729 3,212,424
4,448,915 D 276,993

CAUTION
DO NOT INSTALL UNIT BEFORE READING INSTALLATION AND MAINTENANCE INSTRUCTIONS ATTACHED TO THIS UNIT.
IF UNIT IS TO BE STORED FOR ANY PERIOD OF TIME REFER TO THE INSTALLATION AND MAINTENANCE INSTRUCTIONS FOR PROPER STORAGE.
FOR ANY MAINTENANCE OR ALIGNMENT CHECKS, ELECTRICALLY DISCONNECT THE FAN AND INSURE THAT THE RELAY HAS STOPPED AND THAT THE FAN CANNOT BE RESTARTED.
TO THE DRIVE ELEMENTS CONTACT THE TRANE INSTALLATION.

AHU 2

FIELD LIFTING INSTRUCTIONS
Diagram showing lifting points and instructions for lifting the unit.

44.4
WEISS
MANAGEMENT
2014

