Additional Funding Request

NY127	CSS# 94715 WO# 23773
Description of Repairs	Labor and material to a.) replace (1) Non-functioning Tamper Switch in IDS Vault
Diagnosis: Initial Work Order	**Repair IDS Vault Tamper alarm is indicated.**
Diagnostic Fee	NA
Additional Labor Cost to Perform Repairs	16 x $85.00 = $1360.00
Additional Material Cost to Perform Repairs	<table><tr><td>Materials (See attached detail)</td><td>NA</td><td>139.00</td><td>139.00</td></tr></table>
Total Cost of Repair	$ 1499.00

LoCurrent Systems, LLC
3522 County Highway 11
Cooperstown, NY 13326
(607)293-7300
locurrent@gmail.com

Estimate

ADDRESS

Tidewater Inc.
6625- A Selnick Drive
Elkridge, MD 21075

ESTIMATE # 2315
DATE 08/07/2023

P.O. NUMBER
Nichols, NY Tamper Switch

	ACTIVITY	QTY		AMOUNT
08/07/2023	**Services** Nichols, NY USARC Replace Vault Tamper Switch (CSS#94715) Dear Ms. Demain, As per your request, LoCurrent Systems is please to provide a quotation to replace (1) Non-functional Tamper Switch in IDS Vault at the Nichols, NY USARC and test for proper operation with Ft. McCoy. Cost Breakdown: (1) Tamper Switch..............$139.00 (2) Men 8 hours @ $85......$1360.00 Grand Total........................$1499.00 The cost for the above mentioned work is $1,499.00. If acceptable, please do not hesitate to contact us so we may this work on the schedule. Thank you so much for thinking of LoCurrent Systems. Sincerely,	1	1,499.00	1,499.00

ACTIVITY	QTY	AMOUNT
Antonietta LoRusso		

NY	TOTAL	$1,499.00

Accepted By

Accepted Date