Additional Funding Request

Submitted: 7/9/20

MD002 – Diagnose Intercom System	**CSS #23764 WO# 12470**
Description of Repairs	Additional repairs are needed to trouble shoot system hardware.
Original SC Investigative Diagnosis	
Diagnosis: Initial Work Order	LoCurrent to diagnose the Intercom System.
Explanation of Additional Costs for Repairs	N/A
Additional Material Cost to Perform Repairs	**Materials: N/A** | ITEM	QUANTITY	UNIT PRICE	TOTAL | |---|---|---|---| | | | | |
Additional Labor Cost to Perform Repairs	**Labor: $2,450.00** 2 men / 16 hours each / Rate $75.00 = $2,400.00 Administrative = $50.00
Total Cost of Repair	**$2,450.00**