CMI Management, Inc.

Additional Funding Request

WITH INVOICE

Submitted: **6/08/2022**

MD021 Refrigerant leaking at Chiller Circuit #1	CSS #428 WO#17346
Description of Repairs	Found several leaks on caps to suction and discharge piping. Used sealing compound to seal all caps. Leak checked, all good. Charged system with 10lbs of R410a on both circuits used a total of 10lbs. Work complete.
Original SC Investigative Diagnosis	$NA
Diagnosis: Initial Work Order	: Repair Refrigerant Leak at chiller, Circuit #1 near filter drier
Explanation of Additional Costs for Repairs	N/A
Additional Material Cost to Perform Repairs	**Materials: $ 240.90**
Additional Labor Cost to Perform Repairs	**Labor: $900.00** 9 hours each/HVAC Rate $100.00 per hour = $900.00
Total Cost of Repair	**$1,140.90**

Additional Material Cost to Perform Repairs:

ITEM	QUANTITY	UNIT PRICE	TOTAL
Sealing Compound/R410a Refrigerant	**1**	**$240.90**	**$240.90**