Additional Funding Request

Site: NY023	WO# 20195 CSS # 90937
Description of Repairs	CNTR will install CAC reader
Diagnosis: Initial Work Order	Building 206 card reader repairThe card reader is not accepting code input....however when you hit the keys it tones
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	1224.00
Additional Material Cost to Perform Repairs	1215.00
Total Cost of Repair	$2439.00

LoCurrent Systems, LLC
3522 County Highway 11
Cooperstown, NY 13326
(607)293-7300
locurrent@gmail.com

Estimate

ADDRESS
ISG International Support Group

ESTIMATE # 2143
DATE 11/28/2022

P.O. NUMBER
CSS#90937 WO#20195

ACTIVITY	QTY		AMOUNT
Services Ft. Totten, NY023 USARC Bldg. 206 CSS#90937 WO#20195 Repair/Replace CAC Reader Dear Ms. Dubois: As per your request, LoCurrent Systems is pleased to provide a quotation to Repair/Replace CAC Reader at Building 206 at the Ft. Totten, NY023 USARC. Cost Breakdown: (1) CAC Reader...............................$1,550.00 Core Rebate.....................................($200.00) (2) men 8 hrs @ $85........................$1,360.00 Grand Total.....................................$2,710.00 The cost for the above mentioned work is $2,710.00. If acceptable, please do not hesitate to contact us so that we may schedule for work to be completed. Thank you so much for thinking of LoCurrent Systems. Sincerely,	1	2,710.00	2,710.00

ACTIVITY	QTY	AMOUNT
Antonietta LoRusso		

	TOTAL	**$2,710.00**

Accepted By

Accepted Date