Date:	2-20-24		

Region:	4A	CSS No.:	96821
FAC ID:	PA118	Maximo WO No.:	15194

Asset #:		Priority:	2

Original Work Request:

Repair access control system

Description of Repairs Needed:

Quote is to replace DRM Board (2), CPU Board (1) and Veridt Biometric Reader (1), reconfigure access control server, test all equipment for proper operation and perform re-enrollment to repair the access control system.

Labor:	Labor Hrs	Labor Rate	Total
Tech (2)	54	$ 95.00	$ 5,130.00
			$ -

Material List:	Quantity	Cost	Total
			$ -
			$ -
			$ -
			$ -
			$ -
			$ -
			$ -

Equipment List:	Quantity	Cost	Total
DRM Board (20-0235-10)	2	$ 548.00	$ 1,096.00
CPU Board (20-0635-30)	1	$ 535.00	$ 535.00
Veridt Biometric Reader (less $200 rebate)- 900W2030-WGPON	1	$ 1,350.00	$ 1,350.00

PM WO History:

Estimate Summary:

Labor	Material	Equipment
$5,130.00	$0.00	$2,981.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
$8,111.00	$973.32	$486.66	$9,570.98