CASTO TECHNICAL SERVICES, INC.

SERVICE REPORT

DATE 02/28/2024   ARRIVAL TIME 9:30   DEPARTURE TIME 3:30   JOB/TCK. NO. 202270

CUSTOMER P.O. NO. CSS # 89880

JOB NAME/LOCATION USARC - Beaver WV002

SERVICE REQUESTED *(8) Investment includes labor and materials to replace (6) aif flow pressure transducers and (3) HW valve actuators*

Manufacture: _____	
Model#: _____	
Serial#: _____	
Refrigerant Added:	Qty___ lb___ oz___ TYPE___
Refrigerant Removed:	Qty___ lb___ oz___ TYPE___

☐ Leak Tested

☐ Leak Found

☐ Leak Repaired

Method: _____

Total Charge: _____

WORK PERFORMED/UNIT INFO.

Got on site and checked in with customer. I had already gotten the parts off of Shawn. He said to just look for the cold rooms on rover and then overide the HW valves to on and check the discharge air temp, because it had been over 2 years since he quoted this and couldn't remember what rooms it were. I took my computer in and hooked up to the BCU, found all of the devices on rover and started looking at space temps. Every room was either at or above setpoint, there were no cold rooms (Its been warm outside the last two days.) So, I started one by one overiding hot water valves to on, watching discharge air temp, and then checking rooms to be sure that was the one I was looking at. This was proving that it was going to take quite some time to do by myself,

NATURE OF WORK

Regular Service _____

Quoted Service _____

Start-up/Warranty _____

SPD _____

Contract Service _____

Energy Management _____

PARTS, MATERIALS AND SUBCONTRACTED SERVICES

QTY.	PART NO.	DESCRIPTION	P.L.	VENDOR	

SUMMARY OF TIME

SERVICE TECHNICIAN	ON SITE REG.	ON SITE O.T.	REG. TRAVEL	O.T. TRAVEL	TOTAL HRS.	MEALS	LODGING	TOLLS	MILES	OTHER
1350 Jordan Berry	6		0.50		6.50					
1378 Joseph Harrah	5				5					

JOB COMPLETE   YES _____   NO X   EXPLAIN *more to do*

SIGNATURE _____

Customer Representative

CASTO TECHNICAL SERVICES, INC.

SERVICE REPORT

DATE _____ ARRIVAL TIME _____ DEPARTURE TIME _____ JOB/TCK. NO. _202270_

CUSTOMER P.O. NO. _CSS # 89880_

JOB NAME/LOCATION _USARC - Beaver WV002_

SERVICE REQUESTED _for VAV boxes. W/O 14297_

Manufacture: _____	☐ Leak Tested
Model#: _____	☐ Leak Found
Serial#: _____	☐ Leak Repaired
Refrigerant Added: Qty lb oz TYPE	Method: _____
Refrigerant Removed: Qty lb oz TYPE	Total Charge: _____

WORK PERFORMED/UNIT INFO.

so i had joseph come over and give me a hand. I called Amy and she sent me two roomss that she knew of that were having issues. I had joseph take his ladder and go to those rooms and watch the actuators and feel the supply and return lines on the HW coils while I overrode them on. The first room we checked was operating fine, but the valve was leaking. The second one we checked was not working properly. The actuator was turning but there was no hot water going through the coil. We put a new actuator on it, and then tried it again and still nothing. Took it back apart and lubricated the shaft on the valve body, and pecked down on it a few times trying to free it up, then put it all back together and tried again and still nothing. Grabbed a washing machine hose

NATURE OF WORK

Regular Service _____

Quoted Service _____

Start-up/Warranty _____

SPD _____

Contract Service _____

Energy Management _____

PARTS, MATERIALS AND SUBCONTRACTED SERVICES

QTY.	PART NO.	DESCRIPTION	P.L.	VENDOR	

SUMMARY OF TIME

SERVICE TECHNICIAN	ON SITE REG.	ON SITE O.T.	REG. TRAVEL	O.T. TRAVEL	TOTAL HRS.	MEALS	LODGING	TOLLS	MILES	OTHER

JOB COMPLETE   YES _____ NO _____ EXPLAIN _____

SIGNATURE _____

      Customer Representative

and a bucket, then drove the valve open on rover, and tried bleeding some suspected air off of it (If it wasn't a stuck valve), and got some air out of it, but nonetheless it appeared the valve itself just wasn't opening. I talked to jason and let him know i'd come back tomorrow when it was cold and figure out what all we need. Packed up, did paperwork, and then left.