Additional Funding Request

Submitted: **12/02/2021**

VA002 CAC Reader	CSS #33682 WO#15656
Description of Repairs	As per your request, LoCurrent Systems is pleased to provide a quotation to replace the nonfunctional Main Door Entrance Reader at the Lieber Center in Alexandria, VA VA002.
Original SC Investigative Diagnosis	**N/A**
Diagnosis: Initial Work Order	Main entrance door CAC reader is not working properly. The keypad buttons does not work most of the time. Chris tried to reset reader by unplugging and also tried reset by inserting CAC in backwards.
Explanation of Additional Costs for Repairs	N/A
Additional Material Cost to Perform Repairs	**Materials: $ $1,250.00** <table><tr><td>**ITEM**</td><td>**QUANTITY**</td><td>**UNIT PRICE**</td><td>**TOTAL**</td></tr><tr><td>**Biometric Reader**</td><td>**1**</td><td>**$1,250.00**</td><td>**$1250.00**</td></tr></table>
Additional Labor Cost to Perform Repairs	**Labor: $730.00** 8 hours each/ $85.00 per hour = $680.00 and Admin Fee $50.00=$730.00
Total Cost of Repair	**$1,980.00**