Additional Funding Request

Submitted: 6/4/2020

VA002 – CAC card reader system update	CSS #25410 WO# 12334
Description of Repairs	Flash CAC readers with new firmware. Current CAC readers do not recognize newly issued CAC/ID cards.
Original SC Investigative Diagnosis	**NA**
Diagnosis: Initial Work Order	LoCurrent to perform a system update to accommodate recent deployed G&D CAC 7.0 at the Lieber Center Alexandria, VA USARC.
Explanation of Additional Costs for Repairs	N/A
Additional Administrative Cost to Perform Repairs	**$50.00**
Additional Labor Cost to Perform Repairs	**Labor: $1,200.00** 2 Labor Techs/8 hours each/Rate $75.00 per hour = $600.00
Total Cost of Repair	**$1,250.00**