# CERTIFICATION OF WORK
## PREVENTIVE MAINTENANCE

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: __VA049__          Date of Visit: __11/12/19__

Contractor Personnel on Site:

1. __BOND WATER TECHNOLOGIES__      3. _____
2. __BILL DAVIS__                   4. _____

**Work Performed:**

**Preventive Maintenance** - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. __WO 11209 ASSET 190918-247_____
2. _____
3. _____
4. _____
5. _____

------------------------------------------------------------------------

## CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: __Jon Miller__          Date: __11/12/19__

Signed: __(signature)__

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: __LTC Ryan S. Cook__          Date: __12 Nov 19__

Signed: __(signature)__

-Mail: _____

**Tidewater, INC**
**VA-049**
**6700 Strathmore Rd.**
**North Chesterfield VA  23237**
**(410) 540-8700**

Recorded By:  **Jon Miller**
**(301) 580-9820**
**jmiller@bondwater.com**

## Boiler Room - HVAC Equipment

| Test | Hot Loop | Chill Loop | | |
|------|----------|-----------|---|---|
| Conductivity (as mmhos) | 187 / 3500 max | 830 / 3500 max | | |
| pH | 8.1 / 8 - 10.5 | 8.3 / 8 - 10.5 | | |
| Molybdate (ppm as Mo) | 0 / 50 min | 0 / 50 min | | |

## Opening Comment

Performed quarterly scheduled service visit.

Dropped off filters and filtration housings for the hot and chill water loops, also marked appropriate taps in order to pipe in filtration housings.

### Hot Water Loop                                                                        Online

Corrosion inhibitor residual is low at this time, no regular hose bibs exist on the system in order to pump in corrosion inhibitor. Took note of different valves on the system, will order custom plumbing adapters in order to pump in more corrosion inhibitor into the system.

### Chill Water Loop                                                                      Online

Corrosion inhibitor residual is low at this time, no regular hose bibs exist on the system in order to pump in corrosion inhibitor. Took note of different valves on the system, will order custom plumbing adapters in order to pump in more corrosion inhibitor into the system.