PM-QT-10541

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST
VEHICLE EXHAUST REMOVAL

SITE AND BLDG #: NY060   OMS

LOCATION/RM #: SHOP   **WO#** 1431   **ASSET #** 10541

MECHANIC SIGNATURE: Dave Rennel   **DATE:** 12/18/2018

START TIME: _____   **FINISH TIME:** _____

#	TASK/ITEM DESCRIPTION	TASK COMPLETE YES	NO	NOTES/ACTIONS (TASK COMPLETE IS CHECKED NO, PROVIDE EXPLANATION)
	SAFETY INSTRUCTION			
1	In addition to the procedure(s) outlined in this standard, the equipment manufacturer's recommended maintenance procedure(s) and/or instruction(s) shall be strictly adhered.	X		
2	Follow lock out/tag out procedures at all times. De-energize or discharge all hydraulic, electrical, mechanical, or thermal energy prior to beginning work.	X		
	TO BE PERFORMED DURING INSPECTION/SERVICE			
1	Start and stop fan with local switch	X		
2	Check motor and fan shaft bearings for noise, vibraton, overheating; lubrucate bearings.	X		
3	(Inspect) adjust belts and pulleys. Replace belt as needed.	X		
4	Clean dampers; lubricate pivot points (annually) and inspect linkages for tightness.	X		
5	Inspect fan for bent blades, unbalance, excessive noise and vibration.	X		
6	Clean fan as needed.	X		
7	Visually inspect exaust system tubing and/or duct work for any damage that could result in leaks.	X		
8	Repair as needed		X	ADVISE to Replace hose & electrical part

Note: The technician shall perform any repairs identified during PM up to $250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding $250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed discription of the deficiency.

To be perfomed by: General Maintenance Worker

Additional Notes: This checklist covers 2 unit exhaust removal

Damage to Left side Hose, Completely Ripped/torn, need to replace.
Control to left side unit damaged - electrical retention part brottle - need to replace.
Advise **NOT** to use the unit on the left (west side); Unit on Right (EAST) is 100%.

over