



ANNUAL
EQUIPMENT
INSPECTION

US ARMY RESERVE – Schenectady, New York

HOIST ID: **01**

www.FixMyCrane.com

46 Goode St Burnt Hills, NY 12027
FaceBook.com/TitanCraneAndHoist

1201 HILLSIDE AVE

EQUIPMENT TYPE: Single Girder Top Running Wire Rope Crane

EQUIPMENT MAKE: Robbins and Meyers (R&M)

EQUIPMENT SERIAL NUMBER: HNW35793

Lift: 29.5'

Voltage: 460 VAC

Manufacturer Reference: J4T09515

EQUIPMENT MODEL:

SX50410100P55FDLOS

EQUIPMENT CAPACITY: 10 Ton

EQUIPMENT NOTES OF CONDITION, OPERATION, FIT, LABELS AND CODE VIOLATIONS:

No issues to address regarding safety violations or preventive recommendations.

Current Hook Opening: 2.25" with latch compressed.

TROLLEY MAKE: R&M

TROLLEY CAPACITY: 10 Ton

TROLLEY TYPE: No Trolley

TROLLEY NOTES ON VISUAL INSPECTION OF CONDITION, LABELS, FIT AND OPERATION:

No issues to address.

OVERHEAD LIFTING POINT TYPE: SGTR I Beam

OVERHEAD LIFTING POINT MARKED CAPACITY: **10 Ton**

OVERHEAD LIFTING POINT NOTES OF VISUAL INSPECTION OF CONDITION, LABELS AND END STOPS:

No issues to address.

INSPECTION DATE: 09-03-2020

SIGNING INSPECTOR: Joseph Burchett

Note: **CAPITALIZED ITEMS ARE SAFETY ISSUES THAT MUST BE FIXED IN ORDER FOR HOIST/CRANE TO BE CONSIDERED SAFE TO RETURN TO USE.** All cranes/hoists that are inspected receive an inspection sticker. The presence of a sticker does not indicate that necessary repairs have been made. Ensuring necessary safety issue repairs are made is solely the customer's responsibility. *Italicized items indicate action taken to resolve an issue.*

Shop: (518) 399-9906 • Emergency: (518) 339-5696