

January 6, 2023

NY116 SGT Catalin D Dima AFRC  
910 Raz Ave  
New Windsor, NY 12553

**Re: WO 19757 CSS 90549 AMSA shop boiler repairs.**

Dear Joe,

Thank you for the opportunity to quote.

We propose to furnish the necessary labor, material, and supervision required to supply OEM tool and remove air flapper housing and clean out bees on Fulton boiler serial #107430. Bees found inside while performing work on the inducer motor. Technician inspected roof and found no obstructions.

**Our proposal is based on the following:**

1. Supply OEM tool and leave in procession of USAR on site.
2. Remove air flapper housing.
3. Remove bees obstructing intake.
4. Assemble and test.

**Our proposal excludes the following:**

1. Parts or materials not herein listed.
2. Labor to replace parts or materials not here in listed.
3. Permits or fees.

**The above can be completed for the sum of \$1,694.05 plus any applicable taxes.**  
**Quote valid for thirty days.**

<b>Labor 8 X \$150=.</b>	<b>\$1,200.00</b>
<b>Trip.</b>	<b>\$75.00</b>
<b>Tool \$314.21 X 1.2.</b>	<b>377.05</b>
<b>Freight. \$35.00 X 1.2.</b>	<b>42.00</b>

Please sign where indicated, confirming your acceptance of the above listed work. Kindly fax the signed acceptance to our office, including your Purchase Order Number.

If you should have any questions or require additional information on the above, please do not hesitate to contact us.

Authorized Signature: \_\_\_\_\_ Date: \_\_\_\_\_

Purchase order: \_\_\_\_\_

Yours Truly,  
David Hinnrichs