



June 12, 2023

NY116 SGT Catalin D Dima AFRC
910 Raz Ave
New Windsor, NY 12553

Re: CSS 93728 WO 22718 AHU4T reheat coil

Dear Joe,

Thank you for the opportunity to quote.

We propose to furnish the necessary labor, material, and supervision required to replace leaking di-electric unions on AHU 4T reheat coil.

Our proposal is based on the following:

1. Isolate coil and drain glycol.
2. Replace all di-electric unions on reheat coil.
3. Fill coil with glycol.
4. Test and inspect.

Our proposal excludes the following:

1. Parts or materials not herein listed.
2. Labor to replace parts or materials not here in listed.
3. Permits or fees.

The above can be completed for the sum of \$2,126.83 plus any applicable taxes.
Quote valid for thirty days.

<u>Labor 10 X \$150=.</u>	<u>\$1,500.00</u>
<u>Trip.</u>	<u>\$75.00</u>
<u>Material \$459.86 X 1.2=.</u>	<u>\$551.83</u>

Please sign where indicated, confirming your acceptance of the above listed work. Kindly fax the signed acceptance to our office, including your Purchase Order Number.

If you should have any questions or require additional information on the above, please do not hesitate to contact us.

Authorized Signature: _____ Date: _____

Purchase order: _____

Yours Truly,
David Hinnrichs