

Additional Funding Request

PA209 – Circulation Pump	Maximo WO # 7113 CSS# 16918 Asset# 7103
Description of Repairs	Labor and material to replace the in-floor heating water actuator.
Diagnosis: Initial Work Order	Repair actuator for circulation pump #1 in the motor pool (RM104). Routine request
Explanation of Additional Costs for Repairs	Labor and material to repair the circulation pump.
Investigative Diagnosis from SC	\$360.00 (3 hours x \$120)
Additional Material Cost to Perform Repairs	\$70.00 Valve Actuator Travel Charge (\$1.00 @ 70 miles) \$140.00
Additional Labor Cost to Perform Repairs	\$1080.00 (9 hours x \$120)
Total Cost of Repair	\$1650.00

ZONE24NC

BELIMO


Spring Return - Normally Closed
24VAC, 7VA, Class 2, NEMA 1

Valve Actuator




LISTED
86BP


Wiring Diagram



Open Manual Lever



Attach/Remove



US Pat. 7,048,251

Components Made in USA, Assembled in Italy