

Additional Funding Request

PA118	CSS# 17063 WO# 7179 Asset# 6751
Description of Repairs	Labor and materials to replace, and install a new air filter/ drain assembly, for the air dryer
Diagnosis: Initial Work Order	Air dryer for the compressor needs to be repaired as it is leaking air out of the filter housing that is closest to the back wall. This equipment needed to run tools to repair equipment. The mechanics cannot use any air tools to repair the equipment. Urgent Request
Diagnostic Costs	\$ 360 3 Hours @ \$120/Hr
Additional Labor Cost to Perform Repairs	\$ 690 5 Hours @ \$120/Hr 90 miles @ 1.00/ mile.
Additional Material Cost to Perform Repairs	\$ 350 Replacement Large air filter/drain assembly
Total Cost of Repair	\$ 1,400

WILKERSON®

F30-08-000A E98

KRUMAN EQUIPMENT CO.
PITTSBURGH, PA (412) 261-4847

