

Additional Funding Request

Site: WV022	WO#6420	CSS # 16104	Asset# NA
Description of Repairs	Faucet Seals and Seats are cracked and need to be replaced		
Diagnosis: Initial Work Order CSS# 16104	Water Leaking near Kitchen		
Explanation of Additional Costs for Repairs	Faucet Seals and Seats are cracked and need to be replaced		
Additional Labor Cost to Perform Repairs	7x\$85.00- \$595.00		
Additional Material Cost to Perform Repairs	\$671.36		
Total Cost of Repair	\$1,266.36		