



AH-6 has been blowing fuses fairly regularly for the last 7-10 days. Determine and repair cause. Provide one dozen FRS-R-8 fuses

Proposal is to remove and replace the defective motor and install a new 3hp motor. We will also install fuses and keep 1 box of fuses (12) on site.