

Mini-splits in Rooms 100, 101, 106, and 116 not producing cool air; unit in Rm 115 is noisy during operation; unit in server room leaks condensate back into the room instead of to the outside condensate line on second condenser from the right (when viewed from outside) is deteriorated from weathering; bird's nest in two wall mounted condensers - determine if this is interfering with proper operation.

Troubleshoot Mini-Split units in Multiple Rooms:

*Replace the faulty condensate pump on unit in Server Room (102)

*Replace control board & filter board for condenser supplying Rooms 100, 101 & 106

CMI Cost Estimate								
Funding Request								
PA080 Punxsutawney								
Mini-splits in Rooms 100, 101, 106, and 116								
CSS #14801 - CMI # 5176								
Prepared By: J. Bayne								
1.03.19								