



Asset 6921, Hoisting brake - holding, Hoist brake pad has spline wear and surface is glazed. Needs to be repaired

6921 Crane # 01

Double girder EOT - 1 trolley 1 wire rope hoist, 11 mton, Loc. 171, EWRH 11mton OMI sn 70106 mn
GHD,

CMI Cost Estimate								
Funding Request								
PA171 Johnstown								
Hoisting brake								
CSS #17014 - CMI # 5808								
Prepared By: J. Bayne								
1.03.19								
			Labor			Sub	OHP	
Description	Rate	Hours	Cost	Material	Tax	Total	20%	Total
1. Repair Cost								
1.1 Labor	\$ 112.00	4						\$ 448.00
1.2 Material					\$ -	\$ -	\$ -	\$ 931.00
1.3 Travel								\$448.00
Sub Total Repair Cost								\$ 1,827.00
2. Initial Service Call Investigation								
Grand Total								\$ 1,827.00