

Additional Funding Request

Invoice

VA048	CSS# 22481 WO# 11298 Asset# NA
Description of Repairs	12/10/2019 Work Note Tested all voltage to and within operator. All normal, ran gate 30-40 times. Found ants had taken up residency with the operator. Set bait traps
Diagnosis: Initial Work Order	Main door CAC is not working and the motorized gate is not opening. Soldiers unable to access building from outside with CAC
Diagnostic Fee	\$0
Additional Labor Cost to Perform Repairs	\$ 540 TW Labor 3 hours @ 80/hr LoCurrent See invoice attached. \$300
Additional Material Cost to Perform Repairs	\$0
Total Cost of Repair	\$ 540

LoCurrent Systems, LLC
3522 County Highway 11
Cooperstown, NY 13326
(607)293-7300
locurrent@gmail.com



INVOICE

BILL TO

Tidewater Inc.
6625- A Selnick Drive
Elkridge, MD 21075

INVOICE # 1550
DATE 12/13/2019
DUE DATE 01/12/2020
TERMS Net 30

P.O. NUMBER

Montieth Richmond, VA Gate Op.

DESCRIPTION	QTY	RATE	AMOUNT
Installation CSS#22481 WO# 11298 Montieth Facility Richmond, VA USARC Gate Operator	1	300.00	300.00

LoCurrent Systems arrived on site; Found Gate Operator functioning properly.
Noticed many ants in Gate Operator and control box, suspect ants made their way into
contactor the day of failure causing contactor to not make contact and not function. Put
ant repellent in Gate operator in hopes to deter ants from nesting in electronics.
LoCurrent also cleaned and tested the Gate Operator, metered all voltages and
checked all connections.

Gate functioning properly at the time of departure.

(1) man 4 hours @ \$75.....\$300.00

The cost for the above mentioned work is \$300.00.

If you have any questions regarding this invoice, please contact Antonietta
LoRusso at (607)293-7300.

BALANCE DUE

\$300.00

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: VA 0048

Date of Visit: 12-10-19

Contractor Personnel on Site:

- | | |
|---------------------------------------|----------|
| 1. <u>Bob Nick LoRusso</u> | 4. _____ |
| 2. <u>Ken STAHL</u> | 5. _____ |
| 3. <u>Keith Pearson</u> | 6. _____ |

Service Calls – Service Call Number and Description

- | | |
|-----------------------|-------|
| 1. <u>CSS - 22481</u> | _____ |
| 2. <u>w/o - 11298</u> | _____ |
| 3. _____ | _____ |

Tested All Voltages to & within operator All Normal
RAW Gate 30-40 times
Found Ants HAD taken up residency within

CERTIFICATION OF WORK

the operator. Set bait traps

To be signed by the Contractor:

Print Name: Keith Pearson Date: 12-10-19

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: MAJ Kim Drake Date: 10 Dec 19

Signed: 

E-Mail: _____

USER 3

DL2025/DL2032
CLOCK BATT



City Security

MX000585

VERSION 4.52

S/N 124015

Touch Controller

RADIO OPTIONS

COM OPEN +24V +24V EDGE

Q06 Q07 Q08

SENSOR COM

DO NOT USE

SENSOR 2

DO NOT USE

SENSOR 3

DO NOT USE

CHARGER LOSS

INTERLOCK

DOSE

FR. OPEN

SR

UAL


Q010


Contact Sensor Inputs
Devices UL 325 Listed Only


MX3184-01

10K EDGE
MillerEdge
GEM-104
ON - Obstruction
BLINKING - Fault
PWR MON.
SAFETY









MOTOR
RELAY

STOP BUTTON

OPEN BUTTON

CLOSE BUTTON

REMOTE OPEN AND
RADIO CONTROL

OPEN/CLOSE

DRIVE

MX3183-01

CLASS 2