

## **Additional Funding Request**

Submitted: 7/

<b>MD024 -FT Gate Reader &amp; Aiphone</b>	<b>CSS #28130 WO #13443</b>																
Description of Repairs	During Service call it was discovered that both the Front Gate Reader & AiPhone Pedestals incurred vehicle damage Reader was replaced with new while on site. LoCurrent Systems is pleased to provide a Follow Up Quotation to replace both (2) damaged Pedestals as well as replace damaged Weather shield.																
Original SC Investigative Diagnosis	<b>\$ NA</b>																
Diagnosis: Initial Work Order	Replace (2) damaged Pedestals & Weather shield at the Rockville MD021 Front Gate																
Explanation of Additional Costs for Repairs	N/A																
Additional Material Cost to Perform Repairs	<p><b>Materials: \$691.20</b></p> <table border="1"> <thead> <tr> <th>ITEM</th><th>QUANTITY</th><th>UNIT PRICE</th><th>TOTAL</th></tr> </thead> <tbody> <tr> <td>Pedestals</td><td>2</td><td>\$190.60</td><td>\$381.20</td></tr> <tr> <td>Weather Shield</td><td>1</td><td>\$210.00</td><td>\$210.00</td></tr> <tr> <td>Misc Wire hardware fittings</td><td>1</td><td>\$100.00</td><td>\$100.00</td></tr> </tbody> </table>	ITEM	QUANTITY	UNIT PRICE	TOTAL	Pedestals	2	\$190.60	\$381.20	Weather Shield	1	\$210.00	\$210.00	Misc Wire hardware fittings	1	\$100.00	\$100.00
ITEM	QUANTITY	UNIT PRICE	TOTAL														
Pedestals	2	\$190.60	\$381.20														
Weather Shield	1	\$210.00	\$210.00														
Misc Wire hardware fittings	1	\$100.00	\$100.00														
Additional Labor Cost to Perform Repairs	<p><b>Labor: \$1,250.00</b></p> <p>2 men/8 hrs/Rate \$100.00 hr /Admin Fee \$50 = \$1,250.00</p>																
<b>Total Cost of Repair</b>	<b>\$1,941.20</b>																

**LoCurrent Systems, LLC**

3522 County Highway 11  
 Cooperstown, NY 13326  
 (607)293-7300  
 locurrent@gmail.com



# Estimate

**ADDRESS**

CMI Management  
 5285 Shawnee Road  
 Suite 510  
 Alexandria, VA 22312 USA

**ESTIMATE #** 1712**DATE** 12/18/2020**P.O. NUMBER**

Rockville MD021 Pedestals

	ACTIVITY	QTY	AMOUNT
12/18/2020	<b>Services</b> Follow Up Quotation as per Inv #1813: CSS#28130; WO#13432	1	1,941.20
As per original diagnostic/service call it was discovered that both the Front Gate Reader & AiPhone Pedestals incurred vehicle damage at the Rockville MD021 USARC. Reader was replaced with new while on site.			
LoCurrent Systems is pleased to provide a Follow Up Quotation to replace both (2) damaged Pedestals as well as replace damaged Weathershield.			
Cost Breakdown:			
(2) Pedestals.....\$381.20 (1) Weathershield.....\$210.00 Misc. Wire, Hardware, Fittings, Anchorage etc.....\$100.00 Administrative.....\$50.00 (2) men 8 hrs @ \$75.....\$1,200.00			
Grand Total.....\$1,941.20			

The cost for the above mentioned work is \$1,941.20.

If acceptable, please do not hesitate to contact us so we may get equipment on order.

Thank you for thinking of LoCurrent Systems.

ACTIVITY	QTY	AMOUNT
Sincerely, Antonietta LoRusso		
	TOTAL	<b>\$1,941.20</b>

Accepted By

Accepted Date







