

## Additional Funding Request

NY050	CSS #20103      WO 5052      ASSET # 9949
Description of Repairs	Replace condenser fan motor, blade and capacitor  Check unit for proper operation
Diagnosis: Initial Work Order	repair AC units on roof not running
Explanation of Additional Costs for Repairs	N/A
Additional Labor Cost to Perform Repairs	\$ 624.00.00(5.2mh @120.00/mh)
Additional Material Cost to Perform Repairs	\$733.50
Shipping	N/A
Total Cost of Repair	\$1,357.5