

Argent Inspections

Form AI-03

Boiler Inspection Report

Inspection Date 8/12/2019	Certificate Issued No	Expiration Date	Prepared for Inspection No	Next Watersides/Firesides 2021/2019	Next Strength Test 0
Inspection Type(s) Performed					
<input checked="" type="checkbox"/> Internal <input checked="" type="checkbox"/> Watersides <input checked="" type="checkbox"/> Firesides <input type="checkbox"/> External/Operational <input checked="" type="checkbox"/> Pressure Test <input type="checkbox"/> Strength <input checked="" type="checkbox"/> Tightness					
Customer AMSA Utica NY067			Boiler Location Name and/or Building Number		
Address 95 Burrstone Rd			Boiler Location Address		
City Utica	State NY	Zip 13502	City	State	Zip 0
National Board # 218758	Jurisdiction #	Property #	Boiler Use Closed Heating Loop	Fuel Type Natural Gas	
Manufacturer Lochinvar		Model #		Serial # E09H00218758	Year Built
Capacity 469,000 BTU/HR	Design Pressure 160 psi	Operating Pressure 12-20 psi	Programmer Manufacturer Lochinvar	Burner Manufacturer Lochinvar	
Number of Safety Valves 1	Combustion Efficiency % CO2 ppm CO % Excess O2				Flue Gas Temperature Degrees F
	Valve Manufacturer Watts	Size 3/4"	Set Pressure 50 psi	Capacity 1,352,000 BTU/HR	Lift Pressure
Valve 1					
Valve 2					
Valve 3:					
Valve 4:					
Safety Devices Tested					
Reason(s) for Declining Certification Boiler was inspected internally on the watersides and firesides but would not lite off for operational testing. The circulating pump is not functioning.					
Comments Watersides have a very slight amount of scale. Firesides have some accumulation of dust and particulates. Recommend that intake combustion air filter be replaced. This boiler has been added to the inventory but cannot be certified safe to operate per the Guidance until it will lite off for operational testing.					
Inspector Commission 13314	Inspector Craig H. Bennett	Signature 			
Attachments No	Technical Manager Pages	Signature 			
Jerry Kuykendall					