

Serviced By

**MCKAMISH**

BUILDING EXCELLENCE

A.O. SMITH












Pittsburgh, PA 15235  
(412) 795-3040  
Fax (412) 795-3206

One copy per piece of equipment

Date: \_\_\_\_\_  
Customer Name: Greensburg Army Recrue  
Customer Contact: \_\_\_\_\_  
Address: 400 Amory Drive  
Job Location: Greensburg Pa  
Equipment Type: Exhaust Fan  
Model #: V48V830A1  
Volts 115  
Equipment #: NK  
Filter(s) (qty., size & type): NA  
Belt(s) (qty., size & type): NK  
Accessibility: GFA added  
Evaluation: bearings in motor are bad & it needs to be replaced  
duct work is missing on both sides of exhaust fan  
there is a switch on first floor outside of janitors closet that  
kills all power to fan  
Make: A.O. Smith  
Serial #: 21108411  
Equipment Location: 208  
Area Served: Women's room second floor


Phase 1

coming out of ceiling



also missing a piece of  
8" round duct 7" long

face of fan



Photos Attached: Yes ☐ No ☐  
Status: Incomplete ☐ Complete ☐  
Priority 1-5: ☐ (5 Being High)

Other \_\_\_\_\_  
Date: 11-2-18  
Service Tech: Don

Reviewed By: \_\_\_\_\_  
WHITE - Service Department  
YELLOW - Job File  
PINK - Technician