






SENTRY MECHANICAL

MECHANICAL SYSTEM
EVALUATION

One copy per piece of equipment

Date: 10-16-18
Customer Name: Army Reserve
Customer Contact: [blank]
Job Location: 7100 Leech Farm Rd P5 PA 15206
Equipment Type: PA029-01
Model #: PA029-01
Volts: 115
Equipment #: 7100 ASSET # 6532-Bolt
Filter(s) (qty, size & type):
Accessability:
Evaluation:

Phone #: 724 795-3206
Fax: (412) 795-3206
Job #: PM 367
Phone #: 724 795-3206

Make: HTP
Serial #: 0514128104500
Equipment Location: Bolt AM
Phase: Bolt

On Burner Door around Flame sensor has
an Hole & corrosion, sealed with silicone
looks like sensor wire & Air Channel was
compromised, Flame sensor Ignitor worn
Need to Replace

Burner Door
Air Channel
Burner Throat Gasket
Spark Ignitor
Flame Sensor
Flame Sensor wire

Photos Attached: Yes ☐ No ☐
Other: ☐
Status: Incomplete ☐ Complete ☐
Priority 1-5: ☐ (5 Being High)

Reviewed By: [blank] Date: [blank]
WHITE - Service Department
YELLOW - Job File
PINK - T