

## SERVICE REPORT

CUSTOMER P.O. NO. \_\_\_\_\_

**SERVICE REQUESTED** *Investment is labor to inspect and recertify 1 backflow preventers located at USARC Grafton, WV014.*

Manufacture: <u>Watts</u>				
Model#: <u>909</u>				
Serial#: <u>121935</u>				
Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

☐ Leak Tested

☐ Leak Found

☐ Leak Repaired

Method: \_\_\_\_\_

Total Charge: \_\_\_\_\_

*Arrived and checked in.*

*At site to certify backflow preventer.*

*Hooked up gauges and followed test procedures. The 1st check failed test. Retested several times and it failed every time.*

*Backflow preventer will have to be repaired. I recommend rebuilding entire unit.*

*Will send information to shop to have a repair quote sent to customer.*

Regular Service \_\_\_\_\_  
Quoted Service \_\_\_\_\_  
Start-up/Warranty \_\_\_\_\_  
SPD \_\_\_\_\_  
Contract Service \_\_\_\_\_  
Energy Management \_\_\_\_\_

[illegible][illegible]

JOB COMPLETE YES \_\_\_\_\_ NO X EXPLAIN *Device must be repaired to certify*

SIGNATURE \_\_\_\_\_  
Customer Representative