



OneCIS Insurance Company

95 Oakwood Rd
Lake Zurich, IL 60047
(855) 593-5115
www.us.bureauveritas.com

June 21, 2019

44110-007211.00

Gen Charles C Rogers USARC/OMS
100 Military Dr
South Charleston, WV 25309-8246

HARD COPY

RE: Jurisdictional Inspection:
Gen Charles C Rogers USARC/OMS
100 Military Dr
South Charleston, WV 25309-8246

Thank you for the consideration I received during my visit on May 15, 2019 at your facility listed above. The purpose of the visit was to perform the external inspections of the objects listed below to determine compliance with ASME/National Board rules and regulations. I was accompanied by Wric Ritchie during my visit.

The inspections were performed on behalf of International Support Group (US Army Reserve Offices).

The following objects were inspected at the time of the visit:

Year Built	Type of object	Jurisdictional Number	NB Number	Recommendation(s)
	Cast Iron	WV007-1	CI	See Below
2006	Other	WV007-2	13319	None

The following observations were noted during the inspection of this equipment:

Fittings, attachments, and accessible parts were closely examined and found in satisfactory condition with the exception noted below. No adverse conditions were noted with respect to controls and safety valves.

As a result of this inspection, there was 1 recommendation suggested.

In order for the certificate(s) of operation to be renewed, all code violations must be cleared.

The recommendation(s) made to correct the deficiency(s) are listed below. Please indicate any action(s) taken on these recommendation(s), by calling me at the number listed below.

Based upon this visit, a report of this inspection activity is being forwarded to the governing jurisdiction. That report is requesting new certificates of operation be issued for the object with no adverse conditions noted. The renewal of certificate of operation is being withheld for the objects with code recommendation(s) listed above.

The next inspection is tentatively scheduled to be completed by 07/16/2019.

This document is advisory in nature. Reports or certificates provided in connection with any state-required boiler or pressure vessel inspection do not mean that all hazards or conditions were controlled at the time of the inspection. No liability is assumed by the information contained in this document.

Recommendations

The following recommendation(s) must be completed before an operating permit can be issued.

No. **2019-06-1** - Complete within 30 days
Peerless-WV007-1 located in Boiler Room

Condition: Boiler is Out of Service due to a reported leak. Safety devices appear to be in order.

Requirement: Investigate/repair leak.

Please contact me by phone at 571-373-0998 or by e-mail at william.johnson@onecis.com if there are any questions and to clear any recommendations.

Sincerely,

William Garth Johnson

William Garth Johnson
B&M Jurisdictional Specialist

DISTRIBUTION

Cc:

Jamie Merchant, International Support Group
jmerchant@internationalsupportgroup.com

Thomas Kovach, OneCIS Insurance
Thomas.kovach@onecis.com

FILE