

AMI Services, Inc.
168 Hopper Avenue
Waldwick, NJ 07463
201 447-6750



Work Order Invoice 50010

Date: 12/28/22

Bill to: CMI Management, Inc. 5285 Shawnee Road Suite 510 Alexandria, VA 22312	Job Address: SGT Catalin D Dima AFRC 910 Raz Avenue New Windsor NY 12553
--	--

Customer Code	Payment Terms	Customer PO Number	Quote	Type	Page
19098	Net 30	WO#19757 // CSS# 90549		T	1
Remarks: SGT Catalin D Dima AFRC WO# 61316					

Description of Work Completed

Provided the necessary labor, material, equipment and supervision required to check the heating boiler at AMSA has to be repeatedly reset and will not stay running as specified on our work order report dated November 2nd.

Labor & Equipment Used

Week ending 11/05/22	Sun 10/30	Mon 10/31	Tues 11/1	Wed 11/2	Thur 11/3	Fri 11/4	Sat 11/5	Total Hours	Rate	Extension
R-William G. Rimm				2.50				2.50	155.00	387.50

Other Costs

Description	Extension
Trip Charge	75.00

Invoice Totals:	Labor	Material	Other
	387.50	0.00	75.00

Subtotal: 462.50
Sales Tax: 37.58

Invoice Total: 500.08



Work Order
No: 61316

Armistead Mechanical Inc. Services
168 Hopper Avenue, Waldwick NJ 07463

Date: 11/2/2022
Status: Schedule

Service To: SGT Catalin D Dima AFRC Address: 910 Raz Avenue New Windsor NY 12553	Contact: Phone:
--	----------------------------------

Work Summary

Heating Boiler at AMSA has to be repeatedly reset and will not stay running

Equipment

ID	Description	Type	Make	Model	Serial Number	Location	Year Installed
----	-------------	------	------	-------	---------------	----------	----------------

Labor

Date	Technician	Hours
11/2/2022	20078 (William G. Rimm)	2.50

Parts

Description	Quantity
-------------	----------

Notes

Topic	Note
WORK ORDER NOTES	11/2/22 BR arrived gained access found unit in alarm installed the alarm module to find out what unit is in alarm for found in alarm code 56 = block intake lock out checked intake is clear checked intake motor very noisy bearings going bad and checked intake switch that is bad as well need to replace Intake switch and intake blower motor as per troubleshooting manual Purge motor part #2-30-000445 Intake switch part # 2-30-000232 Fulton boiler Model# PHW-750 National board # 107430

Customer Signature 	Signed By Henry, Anthony	Date 11/2/2022
--	---------------------------------	-----------------------

ATTACHMENT J-0200000-05
FORMS

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY116, AMSA 106

Date of Visit: 20221102

Contractor Personnel on Site:

- | | |
|---------------------------|----------|
| 1. <u>William G. Rimm</u> | 4. _____ |
| 2. _____ | 5. _____ |
| 3. _____ | 6. _____ |

Work Performed:

Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. _____
2. _____
3. _____
4. _____

Inspection, Testing, and Certification

1. _____
2. _____
3. _____
4. _____

Other Recurring Services

1. _____
2. _____
3. _____
4. _____

Service Calls – Service Call Number and Description

1. 61316- unit was in alarm, installed alarm module, code 56- intake lock out, intake clear, intake MTR, bad
2. bearing, intake switch, bad switch. As per service man. requires replacement of intake MTR, Switch. Will
3. quote for replacement of parts

WGO 19757 CSS# 90549

ATTACHMENT J-0200000-05
FORMS

Over and Above Repair Work – Order Number and Description of Work Completed

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: William G. Rimm Date: 11/2/2022

Signed: William G. Rimm

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed:

Print Name/Rank: Anthony Henry Date: 20221102

Signed: HENRY.ANTHONY.MICHAEL.1233780002 Digitally signed by HENRY.ANTHONY.MICHAEL.1233780002
Date: 2022.11.02 09:05:53 -04'00'

E-Mail: anthony.m.henry8.civ@army.mil