

-----Original Message-----

From: Bacani, Paul D CIV USARMY CENAP (US) <Paul.D.Bacani@usace.army.mil>
Sent: Wednesday, July 31, 2019 7:14 AM
To: Steve Miller <steve.miller@cmimgmt.com>
Cc: Bowling, Mark J CW3 USARMY 99 RD (USA) <mark.j.bowling4.mil@mail.mil>; Boyle, Peter J CIV USARMY 99 RSC (US) <peter.j.boyle1.civ@mail.mil>
Subject: RE: 99th FIS FAC ID NY 116 - IDIQ CSS#20417 - CMI WO 5082 - NOTICE TO PROCEED

Steve. The contracting officer approved the following additional work:

Cost is above \$2500

Issue: No power in NYARNG Arms Vaults.

Site NY116
CSS # 20417
CMI WO # 5082
Asset # 10782

Scope: Perform the following repairs to the NYARNG arms vault which has no power:

1. Arms Vaults for Army & National Guard share electrical circuits which are overloaded. Alarm systems for Vaults share the same circuits.
2. Install New circuits to both Vaults and separate electrical circuits.
3. Rewire Alarm circuits to New feeds.

Labor Cost	\$2,700.00
Equipment cost is	\$870.00
Total Cost	\$3,213.00

VR

Paul D. Bacani, AIA, BOCA, RCS
Project Engineer
Contracting Officer Representative
U.S. ARMY CORPS OF ENGINEERS-PHILADELPHIA DISTRICT Construction Branch Central NJ
Resident Engineer Office U.S. Army Corps of Engineers
Tel: (609) 562-2925
Mobile: (609) 508-0037
E-Mail: paul.d.bacani@usace.army.mil