



MASTER LABEL® CERTIFICATE OF INSPECTION FOR LIGHTNING PROTECTION SYSTEMS

Certificate Number
95D9-8A2AAF-1
Inspection Date
30-May-2019
Expiration Date
30-May-2024

This certificate reports the results of a lightning protection system inspection performed by UL LLC. At the time of inspection, the lightning protection system was found to comply with the following requirements.

The inspection was conducted using all applicable sections of standard UL 96A, Installation Requirements for Lightning Protection Systems, Thirteenth edition, issued on 18-Mar-2016.

Structure: US ARMY RESERVE - ADMIN BUILDING
Address: 200 AVIATION DRIVE
JOHNSTOWN, PA 15902
UNITED STATES

Installing Company: WARREN LIGHTNING ROD CO
Address: 2 RICHEY AVE
COLLINGSWOOD, NJ 08107-2306

The following item(s) were omitted from the scope of the Inspection:

Surge protection was not inspected. Surge protection devices are an integral component of a complete lightning protection system and should be provided on all incoming and exiting electric, power, data, and communication services.

UL LLC makes no representations or warranties, expressed or implied, that the lightning protection system will prevent any loss or damage by a lightning event, or that the system will in all cases provide the protection for which it is installed or intended. The certificate is evidence that the installation complies with the installation requirements as outlined in the referenced standard. Valid certificates can be verified on UL's website: <https://lps.ul.com>.

UL LLC is not an insurer and does not assume any obligation or undertake to discharge any liability of the Listed Installing Companies or any other party for any loss, which may result from failure of equipment, incorrect installation, non-conformity with requirements, cancellation of this certificate or withdrawal of the Listed Installing Company from Listing by UL LLC's lightning protection program prior to the expiration date appearing on this certificate.

This certificate is only valid for 5 years. Any modification to electrical, mechanical or communication systems of the structure will affect lightning protection devices and may render protection afforded by this system ineffective. Any changes will invalidate our certificate earlier than the 5 year period.

Bill Costello

Bill Costello

UL Lightning Protection Systems Program Manager



UL and the UL logo are trademarks of UL LLC © 2018
Unauthorized reproduction or alteration of this certificate constitutes fraud.
This certificate is for reference use only.
To verify Master Label® Certificate, please refer to website:
<https://lps.ul.com>