

SENTRY MECHANICAL



24 Hour Service

1724 Leechburg Road
Pittsburgh, PA 15235
Phone: 412-795-3040
Fax: 412-795-3204
Service Fax: 412-795-3206



INVOICE NO
190435V

INVOICE

SOLD TO CMI Management, Inc
c/o Bernard Koblinsky
939 Freeport Road
Natrona Heights, PA 15065

SHIP TO CMI Maryland Boiler relevie v.
14418 McMullen Highway
Cumberland, MD 21502

ACCOUNT NO	PO NUMBER	SHIP VIA	JOB NUMBER	TERMS	INVOICE DATE	PAGE
CMIM001	CSS 15801		181864T	Net 30	6/30/2019	1

RE: MD006 Boiler

CSS 15801
WO 5936

Remove & Replace pressure relief valve on Hot Water Domestic Boiler.

ITEM NO	QUANTITY	DESCRIPTION	UNIT PRICE	EXTENDED
TRUCK	1	Truck Charge	40.00	40.00
LABOR	3:0	*Initial Call* HVAC Service Labor	98.00	294.00
LABOR	8:0	HVAC Service Labor	98.00	784.00
MATERIAL	1:00	Materials	158.22	158.22
MATERIAL	1:00	Piping/Elbows	100.00	100.00
MISC	1	Shipping	24.00	24.00

TOTAL AMOUNT 1,400.22

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: MD006Date of Visit: 1/8/19

Contractor Personnel on Site:

1. _____
2. _____
3. _____
4. _____
5. _____
6. _____

Work Performed: CJS15801-WO#5936

Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. Replaced Boiler Relief Valve
2. _____
3. _____
4. _____

Inspection, Testing, and Certification

1. _____
2. _____
3. _____
4. _____

Other Recurring Services

1. _____
2. _____
3. _____
4. _____

Service Calls – Service Call Number and Description

1. _____
2. _____
3. _____

ATTACHMENT J-0200000-05
FORMS

Over and Above Repair Work – Order Number and Description of Work Completed

CERTIFICATION OF WORK

To be signed by the Contractor.

Signed:

Date: _____

1/8/19

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline.

Print Name/Rank:

Date:

Signed:

E-Mail:







During a scheduled boiler inspection performed by CMI on 09/06/2018 it was discovered that the pressure relief valves on the domestic hot water boiler are leaking and need to be repaired or replaced.

Remove and replace Pressure relief Vale on Hot Water Domestic Boiler