

## **CERTIFICATION OF WORK SERVICE CALL**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: \_\_\_\_\_ Date of Visit: \_\_\_\_\_

#### Contractor Personnel on Site:

1. \_\_\_\_\_
2. \_\_\_\_\_
3. \_\_\_\_\_
4. \_\_\_\_\_
5. \_\_\_\_\_
6. \_\_\_\_\_

### Service Call Number

FEMS# \_\_\_\_\_ WO# \_\_\_\_\_

## Description of Repairs

---

---

---

---

---

## **CERTIFICATION OF WORK**

To be signed by the Contractor:

Print Name: \_\_\_\_\_ Date: \_\_\_\_\_

Signed: \_\_\_\_\_

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: \_\_\_\_\_ Date: \_\_\_\_\_

Signed: John F. Granata

E-Mail:

# POSTLER & JAECKLE

PLUMBING · HEATING · AIR CONDITIONING  
REFRIGERATION · SHEET METAL

24 HR EMERGENCY		1-800-724-4252	
NEW YORK OFFICES			
ROCHESTER	MAIN	585-546-7450	
	SERVICE	585-423-6214	
ALBANY	SERVICE	518-459-0910	
BINGHAMTON	SERVICE	607-757-0100	
SOUTHERN TIER	SERVICE	607-739-8303	
SYRACUSE	SERVICE	315-455-5587	
NEW JERSEY & PENNSYLVANIA	SERVICE	570-883-9563	

**Customer** US ARMY CORPS OF ENGINEERS - PENN YAN (70039)  
**Address** 198 CORNWELL STREET, PENN YAN NY 14527  
**Contact** JOHN GRANATA (585-944-9099)  
**Description** Q ASSESS BOILERS 1&2 FOR REPAIR PO NY052 2897035 WO 17042 NTE \$578.00

## EQUIPMENT

Manufacturer	Model	Serial No.	Location	No.	Desc.	Parts Spec.
Trane	T-6	K4B257166	Ceiling of back office			
Lochinvar	Ftx600n	1846112582922		B1		
Lochinvar	Ftx600n	1846112582919		B2		

## WORK PERFORMED

### Date Description

3/26/2025 Looked at boiler issues that were brought up on the inspectors report. I tested the emergency shut off switches and they both shut the boilers off. I also looked into the high gas pressure switch that was listed in the report. These are factory installed items that are part of the boiler. There is a low water cut off. That's external to the boilers that is no longer wired up. Also boiler zone three pump has a bad bearing assembly. I added oil to the bearing assembly and got it to quiet down some.

## MATERIAL

Category	PO No.	Description
Consumable		oil,

## LABOR

Date	Technician Name	Tech Id	ST	OT	DT	Shift	Remark
3/26/2025	Keith Debolt	91418	3.00				
		Total	3.00				

## TOOL RENTAL

Tool Description	Week Ending	M	T	W	T	F	S	S

## SUBCONTRACTOR

## RECOMMENDATION

Job Status	JOB STATUS COMPLETE	
Accepted By	John	
Tel		Signature
Email		
Comments		
Note: tools and materials may not reflect those listed on the final invoice.		Date

