

ATTACHMENT J-0200000-05
FORMS

Over and Above Repair Work – Order Number and Description of Work Completed

Supply Nipple Broken Boiler #1 Replaced Nipple with
new 1 1/2 x 2 male x male Copper nipple

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Jeffrey Davis Eppley Date: 13 Feb 19

Signed: Jeff Eppley

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed:

Print Name/Rank: JAY Nudds / CW3 Date: 13 Feb 19

Signed: Jay E Nudds

E-Mail: jay.e.nudds.mil@mail.mil



ATTACHMENT J-0200000-05
FORMS

Over and Above Repair Work – Order Number and Description of Work Completed

Supply Nipple Broken Boiler #1 Replaced Nipple with
new 1 1/2 x 2 male x male Copper nipple

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Jeffrey Davis Eppley Date: 13 Feb 19

Signed: Jeff Eppley

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed:

Print Name/Rank: JAY Nudds / CW3 Date: 13 Feb 19

Signed: Jay E Nudds

E-Mail: jay.e.nudds.mil@mail.mil