



BELL & GOSSETT

REDUCING VALVE

12

MODEL NO

SET AT **12 lbs.**

PAT. # 2,899,973

KU

ITT FLUID HANDLING DIVISION
MORTON GROVE, ILLINOIS, U.S.A.
INTERNATIONAL TELEPHONE AND TELEGRAPH CORPORATION

Over and Above Repair Work - Order Number and Description of Work Completed

looked at Fin Tube Radiator in office. found
to have very poor flow. Checked Boiler out
to find system low on water. 9 Psi. - BPS.
Tried to add water but Reducing Valve is bad.

Shut off feed until Replacement.

Also ordered cylinder for Boiler system Main Bldg.

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Justin Zavaacky Date: 2-8-19

Signed: _____

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed:

Print Name/Rank: Esther Date: 2-8-19

Signed: _____

E-Mail: jose.f.lacoste@marl.mil