



Date: 5/26/2023

Region: 4A
FAC ID: NY065

CSS No.: 91875
Maximo Work Order No.: 12762

Asset #: NA

Original Work Request:

The catch basin located by the MEP gate has the pavement falling apart around the catch basin

Description of Repairs Needed:

Labor to inspect and diagnose for repair the Catch Basin located at the MEP Gate which is damaged.

Please note that a follow up quote will be needed upon investigation.

Material List:

NA

Equipment List:

NA

PM WO History:

NA

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
6	\$816.00	\$0.00	\$816.00