

## **CERTIFICATION OF WORK SERVICE CALL**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY067 BLDG1 Date of Visit: 7/20/22

#### Contractor Personnel on Site:

1. Patrick Brown 4. \_\_\_\_\_  
2. \_\_\_\_\_ 5. \_\_\_\_\_  
3. \_\_\_\_\_ 6. \_\_\_\_\_

## Service Call Number

CSS# 1017 WO# 17667


## Description of Repairs

I removed the old dehumidifier that was not working and installed a new dehumidifier and tested for proper operation

## **CERTIFICATION OF WORK**

To be signed by the Contractor:


Print Name: Patrick Brown Date: 7/20/22

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: connery zaleski Date: 7/20/22

Signed: 

E-Mail:

55



# GREEN BULL

PACK 12

	CAPACITY		49.59 pints / 24hr								
	IEF		1.80 L/kW·h								
VOLTS	115	AMPERES	7.2								
PHASE	1	Hz	60								
MODEL NO. ADEL50LZQ1											
USE 15 AMP TIME DELAY FUSE OR CIRCUIT BREAKER	PRESSURE MPa HI DATE OF MFG 02/22 SERIAL NO. DT019776Q	3.6	LO 2.2	R-410A 0.255Kg							
MOTOR-COMPRESSOR THERMALLY PROTECTED MADE IN CHINA											
DEHUMIDIFIER	Scan for Service or Registration										
 US LISTED 2YF9 UL File No. SA7251	<a href="http://www.geappliances.com">www.geappliances.com</a>										
WARNING - RISK OF ELECTRIC SHOCK. DISCONNECT POWER BEFORE SERVICING UNIT.											
WARNING - MOVING PARTS, DO NOT OPERATE UNIT WITH REAR PANEL REMOVED.											
P/N#.:63239906433											

