

Title	VA050 Exit sign needs to be reinstalled
RFOS Region	C10
Facility	VA050-51015-RICHMOND AFRC
Directorate	DPW
Legacy Ticket Number	
Priority Level	Routine (30 days)
Date Created	6/10/2022
Work Description	Maintain
Project Type	Other
SOO	Reinstall exit light on second floor on the left side of building
Additional Comments	
Impact	Limited (Minor repair or functional limitation)
Request Type	FIS-Service Call
Submitter's Name	Angela W Williams-Taylor
Submitter's Phone Number	7575447039
Submitter's Email	angela.w.williams-taylor.ctr@army.mil
On Behalf Of	
Send Copy To	
Work Order Number	
Cost	
Project Cancellation	No
Possible Troop Construction?	No
Possible Self-Help Project?	No
1354?	No
REC Required?	No
Request Status	New Request
Assigned To	☐ ANTONIO.MORONEZ
GPC Type	N/A
Account	N/A
Account Sub-Category	N/A
AMSCO Description	N/A
Vendor 1 Proposal	
Vendor 2 Proposal	
Vendor 3 Proposal	
PR #	
Line #	
Date Funded	
Actual Cost	
Vendor Name	
Vendor Phone Number	
Card Holder	
Billing Official	

Content Type: Item
Version: 1.0
Created at 6/10/2022 6:32 AM by  ANGELA.WILLIAMS-TAYLOR
Last modified at 6/10/2022 6:32 AM by  ANGELA.WILLIAMS-TAYLOR

[https://uroc-redi.usace.army.mil/sites/99th/Lists/CSS Interim/DispForm.aspx?ID=1107&Source=https%3A%2F%2Furoc-redi.usace.army.mil...](https://uroc-redi.usace.army.mil/sites/99th/Lists/CSS%20Interim/DispForm.aspx?ID=1107&Source=https%3A%2F%2Furoc-redi.usace.army.mil...)