

Additional Funding Request

MD003	CSS# 12387 WO# 3330 Asset# 1880																								
Description of Repairs	Labor and materials to repair AC unity in Zone 6.																								
Diagnosis: Initial Work Order	While recent HVAC repair/install project was being worked, there was an additional unit that was found not to be working. The vendor provided an estimate to make the needed repairs. Zone 6																								
Diagnostic Fee	\$ 420 TW Labor \$80/hr x 4 SS Mechanical \$100.00																								
Additional Labor Cost to Perform Repairs	\$ 855 SS Mechanical Labor \$95/hr x 9																								
Additional Material Cost to Perform Repairs	<p>\$ 1,064.99</p> <table border="1"> <tr> <td>Copper piping/3K054/3K050</td> <td>1</td> <td>\$273.78</td> <td>\$273.78</td> </tr> <tr> <td>Installation/6R128</td> <td>1</td> <td>\$60.72</td> <td>\$60.72</td> </tr> <tr> <td>Refrigerant/IR063</td> <td>1</td> <td>\$551.60</td> <td>\$551.60</td> </tr> <tr> <td>Nitrogen/R31</td> <td>1</td> <td>\$24.27</td> <td>\$24.27</td> </tr> <tr> <td>Shipping</td> <td>1</td> <td>\$100.00</td> <td>\$100.00</td> </tr> <tr> <td>Sales Tax</td> <td></td> <td></td> <td>\$54.62</td> </tr> </table>	Copper piping/3K054/3K050	1	\$273.78	\$273.78	Installation/6R128	1	\$60.72	\$60.72	Refrigerant/IR063	1	\$551.60	\$551.60	Nitrogen/R31	1	\$24.27	\$24.27	Shipping	1	\$100.00	\$100.00	Sales Tax			\$54.62
Copper piping/3K054/3K050	1	\$273.78	\$273.78																						
Installation/6R128	1	\$60.72	\$60.72																						
Refrigerant/IR063	1	\$551.60	\$551.60																						
Nitrogen/R31	1	\$24.27	\$24.27																						
Shipping	1	\$100.00	\$100.00																						
Sales Tax			\$54.62																						
Total Cost of Repair	\$ 2,339.99																								