

Region: 5
Location: VA048
CSS #: 18328
Maximo Work Order No.: 1320
Asset #: NA
Date Issued: 7/11/2022
Original Description: The main security gate is stuck in the open position and is beeping loudly. This is an ongoing issue
Repairs Needed:

Labor and Materials to diagnose and repair if possible, Main gate issues at the Monteith VA048. While onsite the technician found Loop Detector Module and Loop are in need of Replacement. Upon arrival at the job found the gate operator in Entrapment Mode; reset operator, adjusted limit switches. Upon further inspection and troubleshooting, found that the Loop Detector Wire shorted out, and although it is operating now, weather conditions can and will affect this operation.

Quantity	Line Item Number	Description	Labor Hours	Labor Rate/Hr	Materials	Equipment	Total
--	--	Materials (See attached for Details)	--	--	\$936.88	--	\$936.88
--	NA	LoCurrent Diagnostic Fee	--	--	--	--	\$450.00
--	NA	LoCurrent Labor Rate (2men @ 12 hrs each)	24	\$85.00	--	--	\$2,040.00
--	NA	TWI Coordination	4	\$80.00	--	--	\$320.00

Estimate Summary:

Labor Hours	Labor Cost	Material Cost	Equipment	Total Cost	CE Factor	Total Estimate
28	\$2,810.00	\$936.88	--	\$3,746.88	106%	\$3,971.70

LoCurrent Systems, LLC

3522 County Highway 11
Cooperstown, NY 13326
(607)293-7300
locurrent@gmail.com



INVOICE

BILL TO

Tidewater Inc.
6625- A Selnick Drive
Elkridge, MD 21075

INVOICE # 2205**DATE** 07/11/2022**DUE DATE** 08/10/2022**TERMS** Net 30**P.O. NUMBER**

Monteith Diagnose Gate

ACTIVITY	QTY	RATE	AMOUNT
Services			
Monteith, VA048	1	450.00	450.00
Diagnose/Repair if Possible Main Gate			
CSS#1320 WO#18328			

Dear Ms. Lowery:

As per your request, LoCurrent Systems is pleased to provide Service to
Diagnose/Repair if Possible Main Gate Issues at the Monteith VA048.

The cost for the above mentioned Diagnosis is \$450.00.

Thank you so much for thinking of LoCurrent Systems.

Sincerely,

Antonietta LoRusso

If you have any questions regarding this invoice, please contact Antonietta
LoRusso at (607)293-7300.

BALANCE DUE

\$450.00

LoCurrent Systems, LLC

3522 County Highway 11
 Cooperstown, NY 13326
 (607)293-7300
 locurrent@gmail.com



Estimate

ADDRESS

Tidewater Inc.
 6625- A Selnick Drive
 Elkridge, MD 21075

ESTIMATE # 2046**DATE** 07/11/2022**P.O. NUMBER**

Follow Up: Monteith

ACTIVITY	QTY	AMOUNT
Services Follow Up Quotation as per Invoice #2205; CSS#1320 WO#18328: Monteith, VA048 Replace Loop Detector Module and Loop	1	2,976.88

Dear Ms. Lowery:

While on site for Service Call CSS#1320 WO#18328; Invoice #2205 at Monteith VA048; technician found Loop Detector Module and Loop are in need of Replacement. Upon arrival at the job found the Gate Operator in Entrapment Mode: reset Operator, adjusted limit switches. Upon further inspection and troubleshooting, found that the Loop Detector Wire was shorted out, and although it is operating now, weather conditions (i.e. rain) can and will affect this operation.

Cost Breakdown:

(1) Loop Detector Module.....	\$186.88
Loop Detector Wire.....	\$175.00
Sealant.....	\$75.00
Saw Cutting Machine (1) Day.....	\$500.00
(2) men 12 hours @	
\$85/hr.....	\$2,040.00

Grand	
Total.....	\$2,976.88

The cost for the above mentioned work is

ACTIVITY	QTY	AMOUNT
\$2,976.88.		
If acceptable, please don't hesitate to contact us so that we may schedule for work to be completed.		
Thank you so much for thinking of LoCurrent Systems.		
Sincerely,		
Antonietta LoRusso		
	TOTAL	\$2,976.88

Accepted By

Accepted Date

**Nationwide Electric Supply**

27 E. 2nd Street

Richmond, VA 23224

National: 800-825-8524 | Local: 804-232-3005

Fax: 804-233-6275 | Support@NationwideElectric.com

www.NationwideElectric.com

Quote

Date	Quote #
07/11/2022	SO-021228

Bill To		Ship To			
Sales Rep	PO Number	Customer Contact	Ship Via	Ship Date	Terms
Davis, Dale		, BRANDON	Customer Pickup		Net 30
Qty	Manufacturer	Catalog Number	PC	Description	Price
1	Square D	A1B3100	100		\$385.00
					Item Total \$385.00
					Tax (0.00%) \$0.00
					Shipping \$10.85
					Grand Total \$395.85

Reference:

Notes:

Thank you for your business.

Signature: _____ Print Name: _____ Date: _____


SUITABLE FOR USE WITH
60°C OR 75°C RATED
CONDUCTOR #4 - #2/0 CU OR
TIGHTEN TO 50 POUND-INCH
INTERRUPTING RATING — INCH
VOLTS
MAX. 240 A.C.
INTERRUPTING RATING — INCH
MAX. 10,000 AMP-S
10,000 SYM.

ON


OFF

100










14506
SUITABLE FOR USE WITH
60°C. OR 75°C. RATED
CONDUCTOR #4, #2/0 CU. OR AL
TIGHTEN TO 50 POUND - INCH
INTERRUPTING RATING
VOLTS MAX. R.M.S. AMPS.
240 A.C. 10,000 SYM.
SQUARE D CO./MADE IN U.S.A.

ON





PANEL P

