

## Additional Funding Request

<b>MD024</b>	<b>CSS# 15664 WO# 6002 Asset# NA</b>
Description of Repairs	Labor and materials to repair and seal chimney stack and seams in metal roof.
Diagnosis: Initial Work Order	Roof leak at penetration above the caged area in bldg. 1003.
Diagnostic Costs	\$ 0
Additional Labor Cost to Perform Repairs	\$ 800  Labor (1) Technician \$100/Hr x 8
Additional Material Cost to Perform Repairs	\$ 130
Total Cost of Repair	\$ 930

# Proposal

MHIC 81777

## PARK HEIGHTS ROOFING, INC.

6999 Reisterstown Road, Suite 1  
Baltimore, MD 21215

www.parkheightsroofing.com



BALTIMORE'S BEST ROOFER  
--Baltimore Magazine

Office # 410-358-1257

### Customer Information:

Tidewater Inc  
6625 Selnick Drive  
Suite A Elkridge, MD 21075

Date	Proposal #
11/16/2018	6904

Home: (703) 565-8472 Cell:

Cell:

E-mail: karlee.demain@tideh2o.net

Item	Proposal	Total
Chimney	720 East Ordnance Road #1003: Repair and seal chimney stack and seams in metal roof.	930.00

Work will start and be completed within 30 days of contract ratification weather permitting. Deposit required at signing of proposal shall be one-third of the contracted amount, with the second-third due upon arrival of materials, and the balance due upon completion of work. A 3% processing fee will be added for credit card transactions. By signing below, homeowner authorizes Park Heights Roofing to process transactions as per agreement. Homeowner is responsible to obtain and purchase any necessary permits. This contract may be cancelled by the home owner within three (3) business days of this signed contract. Due to the frequent price increases of materials, Park Heights Roofing may withdraw this proposal after thirty (30) days if not accepted.

Park Heights Roofing will not be held responsible for indentations in lawn due to debris removal. Park Heights Roofing will not be liable or responsible for any incidental damage or future damage beyond the scope of our work. Park Heights Roofing will not be responsible for any interior work or damage. Park Heights Roofing will not be responsible for interior ceiling nailpops. Park Heights Roofing will not be responsible for damage to existing gutter helmet or gutter guard systems and advise customer have gutter helmet removed prior to roof installation.

Contractor

Date

Owner

Date

**Total** \$930.00

Deposit

Balance

We appreciate your business.

