

Additional Funding Request

DE007	CSS# 16326 WO# 6464 Asset# NA
Description of Repairs	Labor to pick up 55 gal drum of available glycol at MD019 and transport it to DE007 and refill glycol tank. Loading and unloading of glycol will take coordination with the sites so they can assist with fork lifts.
Diagnosis: Initial Work Order	Need to have glycol tank refilled after leaking pipe was repaired. POC is MSG Cox at 910-598-5435 or Mr. Corti at 302-266-5936
Diagnostic Costs	\$ 0
Additional Labor Cost to Perform Repairs	\$ 640 Labor (1) Technician \$80/Hr x 8
Additional Material Cost to Perform Repairs	\$ 0
Total Cost of Repair	\$ 640



WORK ESTIMATE

CSS #: 16326

Work Order #: 6464

Emergency

Urgent

Routine

1

Company Name:	Tidewater, Inc.		Facility ID:	DE007
Contractor POC:	Adam Colopy			
Telephone No:	740-819-6207		Building/Location; (e.g., Classroom/Room #)	Mech Room
E-Mail Address:	adam.colopy@tideh2o.net			
Assigned Technician(s):	John Brown			

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor to pick up 55 gal drum of available glycol at MD019 and transport it to DE007 and refill glycol tank. Loading and unloading of glycol will take coordination with the sites so they can assist with fork lifts.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Labor			8	\$640.00
SUB-TOTAL COSTS:		Materials Total	\$0.00	Labor \$640.00
TOTAL				\$640.00

