

DOUG MOORE

CERTIFICATION OF WORK  
(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: DE001

Date of Visit: 9/30/19

Contractor Personnel on Site:

1. Doug Moore

2. \_\_\_\_\_

3. \_\_\_\_\_

4. \_\_\_\_\_

5. \_\_\_\_\_

6. \_\_\_\_\_

Service Calls – Service Call Number and Description

1. WO# 6463 #16329 Boiler room Push Button shut-down

2. \_\_\_\_\_

3. \_\_\_\_\_

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Doug Moore

Date: 9/30/19

Signed: Doug Moore

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:


Print Name/Rank: Juan Bermudez

Date: 9/30/19

Signed: J. Bermudez

E-Mail: juan.p.bermudezroldan.mil@mail.mil











Boiler  
Contactor

E121488

3/4" COVER

⑤