

Additional Funding Request

| | | | | | | | | | | | | | | | |
|---|---|----------|--|----------|--|---|---|----------|--|----------|-----------|--|--|--|---------|
| DE007 | CSS# 16572 WO# 6834 Asset# NA | | | | | | | | | | | | | | |
| Description of Repairs | <p>Labor and materials to replace two sink faucets and one toilet flush valve.</p> <p>Note: The flush valve will be supplied by the facility.</p> | | | | | | | | | | | | | | |
| Diagnosis: Initial Work Order | <p>It was reported that the water pressure in the restrooms of the OMS building is very low. This is creating issues with the toilets flushing and with the availability of the hand washing sinks. Need to have issue looked at and resolved. POC is MSG Cox at 910-598-5435 or Mr. Corti at 302-266-5936</p> | | | | | | | | | | | | | | |
| Diagnostic Fee | \$0 | | | | | | | | | | | | | | |
| Additional Labor Cost to Perform Repairs | <p>\$ 480</p> <p>TW Labor \$80/hr x 6</p> | | | | | | | | | | | | | | |
| Additional Material Cost to Perform Repairs | <p>\$704.40</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 40%;">Bathroom Faucet, Push Handle - Item # 3RA70</td> <td style="width: 10%;">2</td> <td style="width: 10%;">\$334.10</td> <td style="width: 10%;"></td> <td style="width: 10%;">\$668.21</td> </tr> <tr> <td>Sales Tax</td> <td></td> <td></td> <td></td> <td>\$36.19</td> </tr> </table> | | | | | Bathroom Faucet, Push Handle - Item # 3RA70 | 2 | \$334.10 | | \$668.21 | Sales Tax | | | | \$36.19 |
| Bathroom Faucet, Push Handle - Item # 3RA70 | 2 | \$334.10 | | \$668.21 | | | | | | | | | | | |
| Sales Tax | | | | \$36.19 | | | | | | | | | | | |
| Total Cost of Repair | \$ 1,184.40 | | | | | | | | | | | | | | |



WORK ESTIMATE

CSS #: Work Order #:
Emergency Urgent Routine

| | | | |
|-------------------------|--|---|--------------|
| Company Name: | Tidewater, Inc. | Facility ID: | DE007 |
| Contractor POC: | Adam Colopy | | |
| Telephone No: | 740-819-6207 | Building/Location; (e.g., Classroom/Room #) | OMS Restroom |
| E-Mail Address: | adam.colopy@tideh2o.net | | |
| Assigned Technician(s): | John Brown | | |

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and materials to replace two sink faucets and one toilet fulsh valve.

Note: The flush valve will be supplied by the facility.

| LABOR/MATERIAL | | MATERIAL/ SUB UNIT DOLLAR AMOUNT | LBR/HR \$80 | LINE ITEM TOTAL DOLLAR AMOUNT |
|---|----------|---|-----------------|--|
| ITEM | QUANTITY | | | |
| Labor | | | 6 | \$480.00 |
| Bathroom Faucet, Push Handle - Item # 3RA70 | 2 | \$334.10 | | \$668.21 |
| Sales Tax | | | | \$36.19 |
| SUB-TOTAL COSTS: | | Materials Total | \$704.40 | Labor \$480.00 |
| | | TOTAL | | \$1,184.40 |

MOEN COMMERCIAL

Brass Bathroom Faucet, Push Handle Type, No. of Handles: 2

Item # 3RA70 Mfr. Model # 8886 Catalog Page # 2729 UNSPSC # 40141702



Web Price **\$278.42** / each



One Time Delivery

Add to Cart[+ Add to List](#)

Shipping



Pickup

Expected to arrive **Mon. Dec 03**.

Ship To 43065 (Change)

Jump to:

Replacement Parts

Be the first to write a review

Shipping Weight **5.8 lbs.**Country of Origin **China** | *Country of Origin is subject to change.*

Note: Product availability is real-time updated and adjusted continuously. The product will be reserved for you when you complete your order.

[More](#) **How can we improve our Product Images?** Compare



