

## Additional Funding Request

<b>MD019</b>	<b>CSS# 16748 WO# 6868 Asset# 2062</b>											
Description of Repairs	Labor and materials to install TPI Fan-Forced Electric Heater 5,000 watt 17,100 BTU, Model# HF2B5105N											
Diagnosis: Initial Work Order	Unit Heater requires replacement (Asset #2062)											
Diagnostic Fee	\$0											
Additional Labor Cost to Perform Repairs	<p>\$ 480.00</p> <p>TW Labor \$80/hr x 6</p>											
Additional Material Cost to Perform Repairs	<p>\$562.32</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%;">5,000 watt 17,100 BTU, Model# HF2B5105N</td> <td style="width: 10%;">1</td> <td style="width: 15%;">\$528.00</td> <td style="width: 15%;">\$528.00</td> </tr> <tr> <td>Sales Tax</td> <td></td> <td></td> <td>\$34.32</td> </tr> </table>				5,000 watt 17,100 BTU, Model# HF2B5105N	1	\$528.00	\$528.00	Sales Tax			\$34.32
5,000 watt 17,100 BTU, Model# HF2B5105N	1	\$528.00	\$528.00									
Sales Tax			\$34.32									
PM Credit	(\$250.00)											
Total Cost of Repair	\$ 792.32											



# WORK ESTIMATE

CSS #: **16748** Work Order #: **6868**  
Emergency  Urgent  Routine  X

Company Name:	Tidewater, Inc.	Facility ID:	MD019
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g.,	
E-Mail Address:	<a href="mailto:adam.colopy@tideh2o.net">adam.colopy@tideh2o.net</a>	Classroom/Room #)	
Assigned Technician(s):	John Brown		

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT			
Labor and materials to install TPI Fan-Forceed Electric Heater 5,000 watt 17,100 BTU, Model# HF2B5105N			

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Labor			6	\$480.00
Heater 5,000 watt 17,100 BTU, Model #HF2B5105N	1	\$528.00		\$528.00
Sales Tax				\$34.32
<b>SUB-TOTAL COSTS:</b>		<b>Materials Total</b>	<b>\$562.32</b>	<b>Labor</b> \$480.00
		<b>TOTAL</b>		<b>\$1,042.32</b>

**NORTHERN**  
TOOL + EQUIPMENT

Search

**2X Free Gift Card On All Orders Over \$100**Use Keycode: 262497 | [See Offer Details](#)

Northern Tool > Heaters, Stoves + Fireplaces >  
Electric Heaters > Electric Garage + Industrial Heaters >  
**Item# 53082**

**TPI Fan-Forced Electric Heater — 5,000 Watt,  
17,100 BTU, Model# HF2B5105N****Only \$440.00**(Not Yet Rated - NEW)  
Factory Shipped — Estimated

WARRANTY TAGS	
EQUIPMENT	
MFG NAME	
TAG & LOCATION	UNIT HEATER RAYWALL UH-1 BLDG 2
MODEL NO.	
SERIAL NO.	F2F5105N
TECHNICAL INFO	
DATE INSTALLED	NONE
CONTRACT NO.	208V; 3 PH; 5000W 01/06/2009
WARRANTY PERIOD (FROM / TO)	21-1018-15-01
INSPECTOR'S SIGNATURE	JUNE 11, 2009 - 2010
CONTRACTOR NAME	
WARRANTY CONTACT	L.H. CRANSTON & SONS, INC. 1111 PEPPER RD HUNT VALLEY, MD 21031
WARRANTY RESPONSE TIME PRIORITY CODE	410-252-7100 L.H. CRANSTON & SONS, INC. HUNT VALLEY, MD 21031
WARNING - PROJECT PERSONNEL CODE	410-252-7100
DURING THE WARRANTY PERIOD.	
DURING THE WARRANTY PERIOD.	

