

Additional Funding Request

Submitted: 7/15/22

MD002	CSS 1680 WO 18474			
Description of Repairs	Labor to investigate and repair the BAS that lost communication with the VAV's in most areas			
Original SC Investigative Diagnosis	\$0			
Diagnosis: Initial Work Order	BAS lost communication with VAV's in most areas, temps over 80 degrees. Issue confirmed with Brian, S&S BAS specialist needed			
Explanation of Additional Costs for Repairs	N/A			
Additional Material Cost to Perform Repairs	Materials Cost: \$0			
	ITEM	QUANTITY	UNIT PRICE	TOTAL
	Materials (see attached for details)	1	\$	\$
Additional Labor Cost to Perform Repairs	Labor: \$1044.83 8 hrs/ \$136.60/hr			
Total Cost of Repair	\$1044.83			



SERVICE REPAIR PROPOSAL

Company:

Tustin Mechanical Services

9003 Yellow Brick Road

Baltimore, MD 21237

Ph: 410.803.4300 Fax:

Proposal Date: 7/15/2022

Proposal Number: PSM46438

Customer:

TIDEWATER, INC

6625 SELNICK DRIVE, SUITE A

ELKRIDGE, MD 21075

Shara Fortier

Project Location:

TIDEWATER, INC

6625 SELNICK DRIVE, SUITE A

ELKRIDGE, MD 21075

Shara Fortier

Scope of Work: BAS lost communication with VAV's in most areas, temps over 80 degrees. BAS specialist needed for 8 work hours to locate communication issue.

8 - Trouble Shooting

OUR PRICE FOR THIS PROPOSAL IS\$1,044.83

:

This Proposal does not include premium time, sales tax or additional problems found with the equipment serviced. This proposal is valid for (30) Thirty Days. Thank you for the opportunity to quote this work and we appreciate your business.

Customer Authorization:

Signature (Authorized Representative):

Name (Print/Type):

Date:

Purchase Order #: