

Additional Funding Request

DE007	CSS# 16825 WO# 6889 Asset# NA																			
Description of Repairs	Labor and materials to replace 1 toilet and 1 urinal flush valve and install 2 new sink faucets.																			
Diagnosis: Initial Work Order	1. A urinal flush valve in the mens room on the NG side of the building is not working. 2. The flush valve in the kitchen restroom is not working 3. The 2 sink faucets in the 2nd floor ladies room are not working. The tenants have attempted to change the batteries in all of these but that did not help.																			
Diagnostic Fee	\$0																			
Additional Labor Cost to Perform Repairs	\$ 400 TW Labor \$80/hr x 5																			
Additional Material Cost to Perform Repairs	\$1,195.21 <table border="1" style="margin-top: 10px;"> <tr> <td>1.28 gpf Single Toilet Flush Valve - 1EPE2</td> <td>1</td> <td>\$231.00</td> <td>\$231.00</td> </tr> <tr> <td>0.13 gpf Single Urinal Flush Valve - 6UYN5</td> <td>1</td> <td>\$234.60</td> <td>\$234.60</td> </tr> <tr> <td>Bathroom Faucet, Push Handle - 3RA70</td> <td>2</td> <td>\$334.10</td> <td>\$668.20</td> </tr> <tr> <td>Sales Tax</td> <td></td> <td></td> <td>\$61.41</td> </tr> </table>				1.28 gpf Single Toilet Flush Valve - 1EPE2	1	\$231.00	\$231.00	0.13 gpf Single Urinal Flush Valve - 6UYN5	1	\$234.60	\$234.60	Bathroom Faucet, Push Handle - 3RA70	2	\$334.10	\$668.20	Sales Tax			\$61.41
1.28 gpf Single Toilet Flush Valve - 1EPE2	1	\$231.00	\$231.00																	
0.13 gpf Single Urinal Flush Valve - 6UYN5	1	\$234.60	\$234.60																	
Bathroom Faucet, Push Handle - 3RA70	2	\$334.10	\$668.20																	
Sales Tax			\$61.41																	
Total Cost of Repair	\$ 1,595.21																			



WORK ESTIMATE

CSS #: **16825** Work Order #: **6889**
Emergency Urgent Routine X

Company Name:	Tidewater, Inc.	Facility ID:	DE007
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g., Classroom/Room #)	Various
E-Mail Address:	adam.colopy@tideh2o.net		
Assigned Technician(s):	John Brown		

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and materials to replace 1 toilet and 1 urinal flush valve and install 2 new sink faucets.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Labor			5	\$400.00
1.28 gpf Single Toilet Flush Valve - 1EPE2	1	\$231.00		\$231.00
0.13 gpf Single Urinal Flush Valve - 6UYN5	1	\$234.60		\$234.60
Bthroom Faucet, Push Handle - 3RA70	2	\$334.10		\$668.20
Sales Tax				\$61.41
SUB-TOTAL COSTS:		Materials Total	Labor	\$400.00
			TOTAL	\$1,595.21

MOEN COMMERCIAL

Brass Bathroom Faucet, Push Handle Type, No. of Handles: 2

Item # 3RA70 Mfr. Model # 8886 Catalog Page # 2729 UNSPSC # 40141702



Web Price **\$278.42** / each



One Time Delivery

Add to Cart[+ Add to List](#)

Shipping



Pickup

Expected to arrive **Mon. Dec 03**.

Ship To 43065 (Change)

Jump to:

Replacement Parts

Be the first to write a review

Shipping Weight **5.8 lbs.**Country of Origin **China** | *Country of Origin is subject to change.*

Note: Product availability is real-time updated and adjusted continuously. The product will be reserved for you when you complete your order.

[More](#) **How can we improve our Product Images?** Compare

SLOAN

0.13 gpf Single Flush Urinal Manual Flush Valve, 3/4" IPS Inlet Size, 11-1/2" Rough-In

Item # 6UYRN5 Mfr. Model # Royal 186-0.13 Catalog Page # 2744 UNSPSC # 30181505

Web Price ⓘ
\$195.50 / each One Time Delivery Shipping Pickup

1

Add to Cart

+ Add to List

Expected to arrive **Tue. Dec 18**.

Ship To 43065 (Change)

Be the first to write a review

Shipping Weight 7.35 lbs.

Country of Origin USA | *Country of Origin is subject to change.*

Note: Product availability is real-time updated and adjusted continuously. The product will be reserved for you when you complete your order.
[More](#)

How can we improve our Product Images?

Compare

SLOAN

1.28 gpf Single Flush Toilet Manual Flush Valve, 1" IPS Inlet Size, 11-1/2" Rough-In

Item # 1EPE2 Mfr. Model # Royal 111-1.28 Catalog Page # 2744 UNSPSC # 40141609

Web Price **\$192.50** / each One Time Delivery Shipping Pickup

1

Add to CartExpected to arrive **Tue. Dec 18**.

Ship To 43065 (Change)

Jump to: **Replacement Parts**

Be the first to write a review

Shipping Weight **7.1 lbs.**Country of Origin **USA** | *Country of Origin is subject to change.**Note: Product availability is real-time updated and adjusted continuously. The product will be reserved for you when you complete your order.*
[More](#) How can we **improve our Product Images?**

Compare







