

Additional Funding Request

DE007	CSS# 17122 WO# 7187 Asset# NA															
Description of Repairs	Labor and materials to replace 2 urinal flush valves and install 2 new sink faucets.															
Diagnosis: Initial Work Order	1. There are 2 urinal flush valves (1-mens room floor mens room on NG side, 2nd one 2nd floor mens room) that need repaired. 2. Two restroom sink faucets(middle and right faucet in the 1st floor ladies locker room) that need repaired. The batteries have been changed but the units are still not working.															
Diagnostic Fee	\$0															
Additional Labor Cost to Perform Repairs	<p>\$ 480</p> <p>TW Labor \$80/hr x 6</p>															
Additional Material Cost to Perform Repairs	<p>\$1,199.01</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%;">0.13 gpf Single Urinal Flush Valve - 6UYN5</td> <td style="width: 10%;">2</td> <td style="width: 10%;">\$234.60</td> <td style="width: 10%;">\$469.20</td> </tr> <tr> <td>Bthroom Faucet, Push Handle - 3RA70</td> <td>2</td> <td>\$334.10</td> <td>\$668.20</td> </tr> <tr> <td>Sales Tax</td> <td></td> <td></td> <td>\$61.61</td> </tr> </table>				0.13 gpf Single Urinal Flush Valve - 6UYN5	2	\$234.60	\$469.20	Bthroom Faucet, Push Handle - 3RA70	2	\$334.10	\$668.20	Sales Tax			\$61.61
0.13 gpf Single Urinal Flush Valve - 6UYN5	2	\$234.60	\$469.20													
Bthroom Faucet, Push Handle - 3RA70	2	\$334.10	\$668.20													
Sales Tax			\$61.61													
Total Cost of Repair	\$ 1,679.01															



WORK ESTIMATE

CSS #: **17122** Work Order #: **7187**
Emergency Urgent Routine X

Company Name:	Tidewater, Inc.	Facility ID:	DE007
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g., Classroom/Room #)	Various
E-Mail Address:	adam.colopy@tideh2o.net		
Assigned Technician(s):	John Brown		

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and materials to replace 2 urinal flush valves and install 2 new sink faucets.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Labor			6	\$480.00
0.13 gpf Single Urinal Flush Valve - 6UYN5	2	\$234.60		\$469.20
Bthroom Faucet, Push Handle - 3RA70	2	\$334.10		\$668.20
Sales Tax				\$61.61
SUB-TOTAL COSTS:		Materials Total	\$1,199.01	Labor \$480.00
		TOTAL		\$1,679.01

MOEN COMMERCIAL

Brass Bathroom Faucet, Push Handle Type, No. of Handles: 2

Item # 3RA70 Mfr. Model # 8886 Catalog Page # 2729 UNSPSC # 40141702

Web Price **\$278.42** / each

One Time Delivery

Add to Cart[+ Add to List](#)

Shipping



Pickup

Expected to arrive **Mon. Dec 03**.

Ship To 43065 (Change)

Jump to:

**Replacement Parts**

Be the first to write a review

Shipping Weight **5.8 lbs.**Country of Origin **China** | *Country of Origin is subject to change.**Note: Product availability is real-time updated and adjusted continuously. The product will be reserved for you when you complete your order.*
[More](#)

How can we improve our Product Images?

 Compare

SLOAN

0.13 gpf Single Flush Urinal Manual Flush Valve, 3/4" IPS Inlet Size, 11-1/2" Rough-In

Item # 6UYRN5 Mfr. Model # Royal 186-0.13 Catalog Page # 2744 UNSPSC # 30181505

Web Price **\$195.50** / each One Time Delivery 1**Add to Cart**[+ Add to List](#) Shipping PickupExpected to arrive **Tue. Dec 18**.

Ship To 43065 (Change)

Be the first to write a review

Shipping Weight 7.35 lbs.

Country of Origin **USA** | *Country of Origin is subject to change.**Note: Product availability is real-time updated and adjusted continuously. The product will be reserved for you when you complete your order.*
[More](#)

How can we improve our Product Images?

 Compare



