

Additional Funding Request

MD002	CSS# 17504 WO# 7529 Asset# N/A																			
Description of Repairs	Labor and materials to repair lights in mens shower area of the locker room.																			
Diagnosis: Initial Work Order	Light in men's shower area of the locker room not working.																			
Diagnostic Fee	<p>\$ 80</p> <p>TW Labor \$80/hr x 1</p>																			
Additional Labor Cost to Perform Repairs	<p>\$ 480</p> <p>TW Labor \$80/hr x 6</p>																			
Additional Material Cost to Perform Repairs	<p>\$ 516.08</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 60%;">#5GVC0 GE Electronic Ballast, 32 Max lamp watts</td> <td style="width: 10%;">5</td> <td style="width: 10%;">\$29.22</td> <td style="width: 10%;">\$146.10</td> </tr> <tr> <td>#1PGZ9 GE 26 watts plug-in CFL, T4 PL 4-in(GX24Q-3)</td> <td>6</td> <td>\$30.43</td> <td>\$182.58</td> </tr> <tr> <td>#1PGZ5 GE18.0 watts plug-in CFL, T4PL 4-pin(GX24Q-2)</td> <td>8</td> <td>\$20.11</td> <td>\$160.88</td> </tr> <tr> <td>Sales Tax</td> <td></td> <td></td> <td>\$26.52</td> </tr> </table>				#5GVC0 GE Electronic Ballast, 32 Max lamp watts	5	\$29.22	\$146.10	#1PGZ9 GE 26 watts plug-in CFL, T4 PL 4-in(GX24Q-3)	6	\$30.43	\$182.58	#1PGZ5 GE18.0 watts plug-in CFL, T4PL 4-pin(GX24Q-2)	8	\$20.11	\$160.88	Sales Tax			\$26.52
#5GVC0 GE Electronic Ballast, 32 Max lamp watts	5	\$29.22	\$146.10																	
#1PGZ9 GE 26 watts plug-in CFL, T4 PL 4-in(GX24Q-3)	6	\$30.43	\$182.58																	
#1PGZ5 GE18.0 watts plug-in CFL, T4PL 4-pin(GX24Q-2)	8	\$20.11	\$160.88																	
Sales Tax			\$26.52																	
Total Cost of Repair	\$ 1,076.08																			



WORK ESTIMATE

CSS #: Work Order #:
Emergency Urgent Routine X

Company Name:	Tidewater, Inc.	Facility ID:	MD002
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g.,	
E-Mail Address:	adam.colopy@tideh2o.net	Classroom/Room #)	
Assigned Technician(s):	John Brown		

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT			
Labor and materials to repair lights in mens shower area of the locker room.			

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Labor			6	\$480.00
#5GVC0 GE Electronic Ballast, 32 Max lamp watts	5	\$29.22		\$146.10
1PGZ9 GE 26 watts plug-in CFL, T4 PL 4-pin(GX24Q-3)	6	\$30.43		\$182.58
1PGZ5 GE18.0 watts plug-in CFL,T4PL 4-pin(GX24Q-2)	8	\$20.11		\$160.88
Sales Tax				\$26.52
Diagnostic			1	\$80.00
SUB-TOTAL COSTS:		Materials Total	\$516.08	Labor \$560.00
			TOTAL	\$1,076.08

Johnny Brown ✓
 Tidewater inc.
 740 Trenton Ave
 Severna Park MD 21146-3908
 USA

R4

17504 / 7529

MD002

Shipping Method

Standard FREE

Products in Quote

[Add Products to List](#)[Back to Home Page](#)

Product	Quantity	Availability	Total Price
 Electronic Ballast, 32 Max. Lamp Watts, 120/277 V, Ins GE LIGHTING Electronic Ballast, 32 Max. Lamp Watts, 120/277 V, Instant	5	Expected to arrive Mon. Feb 04.	\$121.75
Item: # 5GVC0			
Your Price \$24.35 / each			
 26 Watts Plug-In CFL, T4 PL, 4-Pin (GX24Q-3),&#x GE LIGHTING 26 Watts Plug-In CFL, T4 PL, 4-Pin (GX24Q-3), 1800 Lumens 3500K Bulb	6	Expected to arrive Mon. Feb 04.	\$152.16
Color Temp.			
Item: # 1PGZ9			
Your Price \$25.36 / each			
 18.0 Watts Plug-In CFL, T4 PL, 4-Pin (GX24Q-2),& GE LIGHTING 18.0 Watts Plug-In CFL, T4 PL, 4-Pin (GX24Q-2), 1200 Lumens 3500K Bulb	8	Expected to arrive Mon. Feb 04.	\$134.08
Color Temp.			
Item: # 1PGZ5			
Your Price \$16.76 / each			

Quote Summary

Expiration Date: 03/02/2019

[View as PDF](#)

Subtotal
\$407.99
 Estimated Tax
\$24.48
 Standard Parcel Shipping
FREE
 Other Shipping
N/A


[Availability, shipping, tax & promotions](#) in this quote are not final until you complete your order.

[Terms of Access](#)
[New Terms of Sale](#)
[New Privacy Policy](#)

[Sitemap](#)
[Fraud Alert](#)

© 1994 - 2019, W.W. Grainger, Inc. All Rights Reserved.





Biax® T/E
F26TBX/835/A/ECO
Made in Hungary

